

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, सिवान-2

पत्रांक.....1611 अनु०..... सिवान, दिनांक.....22/08/2022

प्रेषक,

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, सिवान-2

सेवा में,

सचिव-सह-प्राधिकृत पदाधिकारी
बिहार ग्रामीण पथ विकास एजेन्सी
भूमि विकास बैंक भवन
बुद्ध मार्ग, पटना।


विषय:- योजना शीर्ष नई अनुरक्षण निति 2018 MR/3054 अन्तर्गत पथों में मरम्मत हेतु
अधियाचना के संबंध में।

महाशय,

उपर्युक्त विषयक प्रासंगिक पत्र के आलोक में कहना है कि योजना शीर्ष नई अनुरक्षण
निति 2018 MR/3054 अन्तर्गत संलग्न विहित प्रपत्र में 74.04934 लाख (चौहतर लाख चार
हजार नौव सौ चौतीस) रुपये मात्र आवंटन देने की कृपा की जाय।

अनु०-अधियाचना पत्र, Bump Integrator Equipment Report की छाया प्रति,
एकरारनामा की छाया प्रति,

विश्वासभाजन


कार्यपालक अभियंता
ग्रामीण कार्य विभाग, कार्य प्रमंडल,
सिवान-2
18.8.22

Requisition Format for Scheme Head - MR (3054) Under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

Name of Works Division :- RWD, WORKS DIVISION, SIWAN-2


S.N.	Package No.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative Approval (AA)		Agreement Amount (in Lakh)		Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of HHI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Percentage	Previous Total Allocated Amount (in Lakh)	Up-to-date expenditure as per MIS (in Lakh)	Requisition against work done (in Lakh)	Remarks
					Length (in Km)	Amount (in Lakh)	Initial Rectification with Surface Renewal (in Lakh)	5 Year Routine Maintenance (in Lakh)										
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1	MIR-N 1920siwan-208	Sarwar Gondi to Chinnarawan	31400602021	5139/24.09.19	3.750	125.909	76.24934	35.1832	184MBD of 2020-21/12.04.21	05.08.22	09.06.22	Good	25mm	5.032	0	0	74.04934	Complete
Total															0	0	74.04934	

प्रमाणित किया जाता है कि पथ में कराये गये कार्य के सभी अवयववार 100 प्रतिशत कार्य का दर्ज मापी का सत्यापन संबंधित कनीय अभियंता 50 प्रतिशत मापी का सत्यापन संबंधित सहायक अभियंता एवं 10 प्रतिशत मापी का सत्यापन अद्योहस्ताक्षरी यथा कार्यपालक अभियंता द्वारा किया जा चुका है। कराया गया कार्य मानक एवं विशिष्टियों के अनुरूप है।


18/08/22
कनीय अभियंता
ग्रामीण कार्य विभाग, कार्य प्रवर्द्धन
सिवान-2


18/08/22
सहायक अभियंता
ग्रामीण कार्य विभाग, कार्य प्रवर्द्धन
सिवान-2


18/08/22
प्रमुख लेखा अधिकारी
ग्रामीण कार्य विभाग, कार्य प्रवर्द्धन
सिवान-2


Executive Engineer
RWD Works Division
18-8-22

FORM GFR 19-A

(See Government of India's Decision (I) below Rule-150)

Form of Utilisation Certificate up to 18th July 2022**NEW MAINTENANCE POLICY (2018)**

Name of Scheme	Sanction No.& Date with Amount, (in Rs. Lacs)	Amount Received (in Rs. Lacs)	Particulars
Construction of Rural roads under NEW MAINTENANCE POLICY (2018)	24/19.03.2020	309.44834	Certified that out of Rs 3568.95775 lacs received during the years 2021-22 in favour of Ex. Engineer, RWD, Works Division, siwan-2 Bihar, a sum of Rs 3567.47740 Lacs has been utilized for the purpose of NEW MAINTENANCE POILCY-2018 Schemes as given in the margin for which it was sanctioned and that the balance of Rs 1.48035 lacs remaining unutilized at the end of the period under.
	59/18.08.2020	40.85500	
	78/29.10.2020	127.93990	
	82/13.11.2020	129.95438	
	86/11.12.2020	140.17554	
	05/12.01.2021	246.86987	
	17/26.02.2021	257.50061	
	20/19.03.2021	46.15519	
	26/15.04.2021	70.50399	
	52/24.08.2021	58.39236	
	58/27.10.2021	177.05420	
	60/09.11.2021	87.58854	
	64/06.12.2021	1.27421	
	68/23.12.2021	167.06400	
	02/03.01.2022	614.19943	
	05/25.01.2022	279.43486	
	10/21.02.2022	11.26696	
	18/11.03.2022	726.24067	
	01/20.05.2022	62.42914	
	22/08.08.2022	272.11117	
Total :		3568.95775	

2. Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kind of Checks exercised :-

- Works have been supervised by Executive Engineer/Superintending Engineer.
- Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
- Construction materials have been tested.
- Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/ Executive Engineer.
- All other codal formalities have been observed.

3. **Physical Progress achieved :-**

- Construction of Road works.
- Construction of CD works.

18/8/22
DAO
RWD, WORKS DIVISION
SIWAN-2

12/8/22
EXECUTIVE ENGINEER
RWD, WORKS DIVISION

18.8.22
SIWAN

Name of work : Sanwar Gondi - Chilimawa

Name of customer : AMIT KUMAR CHATURVEDI

(R)Rural Road

Good

Average

Poor

< 4000

4001 - 5000

> 5000

Date	Time	Test No	Distance(m)	Total Distance(m)	BUM(%)	Speed(Km/Hr)	Ultrasonic (mm/Km)	Corrected UI (mm/Km)	IRI	Status	Latitude	Direction	Longitude	Direction	Remarks
14/08/22	11:49:59	94	100	100	23.0 cm	13.1 Km/Hr	2300.0 mm/Km	2332	3.22	Good	26.2107703	N	84.0666971	E	Normal
14/08/22	11:50:37	94	100	200	28.0 cm	19.0 Km/Hr	2800.0 mm/Km	2784	3.77	Good	26.2117243	N	84.0667810	E	Normal
14/08/22	11:51:18	94	100	300	36.0 cm	19.0 Km/Hr	3600.0 mm/Km	3507	4.63	Good	26.2125902	N	84.0669413	E	Normal
14/08/22	11:51:48	94	100	400	32.0 cm	12.1 Km/Hr	3200.0 mm/Km	3145	4.2	Good	26.2133799	N	84.0671549	E	Normal
14/08/22	11:52:10	94	100	500	18.0 cm	16.0 Km/Hr	1800.0 mm/Km	1880	2.65	Good	26.2144098	N	84.0673685	E	Normal
14/08/22	11:52:50	94	100	600	13.0 cm	19.0 Km/Hr	1900.0 mm/Km	1428	2.08	Good	26.2146940	N	84.0680323	E	Normal
14/08/22	11:53:12	94	100	700	22.0 cm	16.3 Km/Hr	2200.0 mm/Km	2241	3.11	Good	26.2146692	N	84.0690470	E	Normal
14/08/22	11:53:33	94	100	800	23.0 cm	17.2 Km/Hr	2300.0 mm/Km	2332	3.22	Good	26.2149954	N	84.0699701	E	Normal
14/08/22	11:53:56	94	100	900	25.0 cm	15.6 Km/Hr	2500.0 mm/Km	2512	3.44	Good	26.2150774	N	84.0710306	E	Normal
14/08/22	11:54:20	94	100	1000	25.0 cm	15.0 Km/Hr	2500.0 mm/Km	2512	3.44	Good	26.2150774	N	84.0720072	E	Normal
14/08/22	11:54:41	94	100	1100	23.0 cm	17.1 Km/Hr	2300.0 mm/Km	2332	3.22	Good	26.2150602	N	84.0729990	E	Normal
14/08/22	11:55:02	94	100	1200	15.0 cm	17.6 Km/Hr	1500.0 mm/Km	1608	2.31	Good	26.2149992	N	84.0740442	E	Normal
14/08/22	11:55:24	94	100	1300	25.0 cm	15.7 Km/Hr	2500.0 mm/Km	2512	3.44	Good	26.2146406	N	84.0747080	E	Normal
14/08/22	11:55:49	94	100	1400	31.0 cm	15.0 Km/Hr	3100.0 mm/Km	3055	4.09	Good	26.2140303	N	84.0752802	E	Normal
14/08/22	11:56:17	94	100	1500	21.0 cm	12.7 Km/Hr	2100.0 mm/Km	2151	2.99	Good	26.2136164	N	84.0760279	E	Normal
14/08/22	11:56:58	94	100	1600	36.0 cm	18.9 Km/Hr	3600.0 mm/Km	3507	4.63	Good	26.2130213	N	84.0764322	E	Normal
14/08/22	11:57:28	94	100	1700	23.0 cm	16.6 Km/Hr	2300.0 mm/Km	2332	3.22	Good	26.2120905	N	84.0762720	E	Normal
14/08/22	11:57:47	94	100	1800	28.0 cm	19.4 Km/Hr	2800.0 mm/Km	2784	3.77	Good	26.2112226	N	84.0761042	E	Normal
14/08/22	11:58:07	94	100	1900	31.0 cm	17.4 Km/Hr	3100.0 mm/Km	3055	4.09	Good	26.2102985	N	84.0759439	E	Normal
14/08/22	11:58:26	94	100	2000	30.0 cm	20.2 Km/Hr	3000.0 mm/Km	2864	3.99	Good	26.2093916	N	84.0757532	E	Normal
14/08/22	11:58:50	94	100	2100	29.0 cm	15.6 Km/Hr	2900.0 mm/Km	2874	3.88	Good	26.2086267	N	84.0759745	E	Normal

14/08/2022
14/08/2022

14/08/2022

14/08/2022

Name of work : Sarwar Gondi - Chilmanwa
 Name of customer : AMIT KUMAR CHATURVEDI

(R)Rural Road			
Good		Average	Poor
< 4000		4001 - 5000	> 5000

14/08/22	11:59:39	94	100	2200	32.0 cm	17.2 Km/Hr	3200.0 mm/Km	3145	4.2	Good	26.2078142	N	84.0780128	E	Normal
14/08/22	12:00:11	94	100	2300	27.0 cm	11.3 Km/Hr	2700.0 mm/Km	2893	3.88	Good	26.2069502	N	84.0781270	E	Normal
14/08/22	12:01:00	94	100	2400	32.0 cm	17.2 Km/Hr	3200.0 mm/Km	3145	4.2	Good	26.2064581	N	84.0783712	E	Normal
14/08/22	12:01:31	94	100	2500	33.0 cm	12.0 Km/Hr	3300.0 mm/Km	3236	4.31	Good	26.2058477	N	84.0787450	E	Normal
14/08/22	12:01:56	94	100	2600	31.0 cm	18.1 Km/Hr	3100.0 mm/Km	3055	4.09	Good	26.2052336	N	84.0786916	E	Normal
14/08/22	12:02:19	94	100	2700	30.0 cm	17.1 Km/Hr	3000.0 mm/Km	2964	3.99	Good	26.2046804	N	84.0777521	E	Normal
14/08/22	12:02:45	94	100	2800	25.0 cm	18.2 Km/Hr	2500.0 mm/Km	2512	3.44	Good	26.2039156	N	84.0779505	E	Normal
14/08/22	12:03:16	94	100	2900	30.0 cm	20.2 Km/Hr	3000.0 mm/Km	2964	3.99	Good	26.2039316	N	84.0757532	E	Normal
14/08/22	12:03:50	94	100	3000	29.0 cm	15.6 Km/Hr	2900.0 mm/Km	2874	3.88	Good	26.2086267	N	84.0759745	E	Normal
14/08/22	12:04:09	94	100	3100	32.0 cm	17.2 Km/Hr	3200.0 mm/Km	3145	4.2	Good	26.2078142	N	84.0760126	E	Normal
14/08/22	12:04:43	94	100	3200	27.0 cm	16.3 Km/Hr	2700.0 mm/Km	2693	3.66	Good	26.2069502	N	84.0761270	E	Normal
14/08/22	12:05:12	94	100	3300	32.0 cm	17.2 Km/Hr	3200.0 mm/Km	3145	4.2	Good	26.2064581	N	84.0763712	E	Normal
14/08/22	12:05:49	94	100	3400	33.0 cm	16.0 Km/Hr	3300.0 mm/Km	3236	4.31	Good	26.2058477	N	84.0767450	E	Normal
14/08/22	12:06:16	94	100	3500	31.0 cm	14.1 Km/Hr	3100.0 mm/Km	3055	4.09	Good	26.2052336	N	84.0769916	E	Normal
14/08/22	12:06:55	94	100	3600	32.0 cm	15.1 Km/Hr	3200.0 mm/Km	3145	4.2	Good	26.2046804	N	84.0777521	E	Normal
14/08/22	12:07:11	94	100	3700	25.0 cm	14.2 Km/Hr	2500.0 mm/Km	2512	3.44	Good	26.2039156	N	84.0779505	E	Normal


Signature
 14/08/22
 S.B

Tik
 14/08/22
 A.E

Signature
 14/08/22

4500

Name of Customer: AMIT KUMAR CHATURVEDI, Machine no: 19208, Road: Sarwar Goudi - Chikmanra, Date: 14-08-22, Section No: 94, Equation: $Y=0.904X+252.3$



[Signature]
14/08/22
A.C.

[Signature]
14/08/22
A.C.

[Signature]
14/8/22