

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, दलसिंहसराय।

पत्रांक:-

1434 (कव)

दिनांक:- 25/8/2022

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, दलसिंहसराय

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी,
सचिव -सह- प्राधिकृत पदाधिकारी, बिहार
ग्रामीण पथ विकास ऐजेंसी पटना।

विषय-

MR New Maintenance Policy 2018 योजनान्तर्गत 5 पथों का पॉचवर्षीय अनुरक्षण का आवंटन
उपलब्ध कराने के संबंध में।

महाशय,

उपरोक्त विषय के संबंध में कहना है कि MR New Maintenance Policy 2018 योजनान्तर्गत
पॉचवर्षीय अनुरक्षण के पथों का पथवार मॉगी जानेवाली आवंटन की सूची Quarter Wise इस पत्र के
साथ संलग्न कर आवश्यक कार्रवाई हेतु समर्पित की जाती है।

अतः अनुरोध है कि उक्त पथों में आवंटन उपलब्ध कराने की कृपा की जाय।

अनु०- 1) अधियाचना प्रपत्र।

2) 19ए फॉर्म।

3½ IRI Report की छायाप्रति संलग्न।

विश्वासभाजन

कार्यपालक अभियंता

ग्रामीण कार्य विभाग

कार्य प्रमंडल, दलसिंहसराय

FORM GFR -19 -A

(see Govt. of India's decision (i) below rule 150)

Form of Utilisation Certificate upto the Month of June 2022

New Maintenance Policy -2018

PIO:- R.W.D. Works, Division , Dalsinghsarai

Month : June 2022

Sl. No.	Name of Scheme	Sanction No.& Date with amount (in Rs. Lacs)	Amount Received (in Rs. Lacs)	Particulars
1	2	3	4	5
1	Maintenance of Rural Road Under New Maintenance Policy - 2018 MR- 3054	14/18.7.2022 (748033)	748033.00	Certified that out of Rs-748033 lacs received during the year's 2022-23 in favour of Ex-Engineer, R.W.D. Works Division, Dalsinghsarai a sum of Rs.0.00 lacs has been utilized for the purpose of New Maintenance Policy -2018 as given in the margine for which it was sanctioned and that the balance of Rs-748033 remaining unutilized at the end of the period under the time of completion.
		0.00	748033.00	

2 Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have


Kind of Checks Exercised :-

- (i) Workers have been supervised by Executive Engineer/ Superintending Engineer
- (ii) Periodical inspection has been conducted by Executive Engineer/Superintending Engineer
- (iii) Construction materials have been tested.
- (iv) Measurments have been recorded in the MB's and test check conducted by the Assistant
- (v) All other codal formalities have overserved

3 Physical Progress Achieved.

- (i) Construction of Road Works
- (ii) Construction of CD Works.

SR. D.A.O
Rural Works Division
Works Division, Dalsinghsarai


Executive Engineer
Rural Works Division
Works Division, Dalsinghsarai

STANDRAD FORMAT FOR ROADS QUARTERLY STATEMENT

PIU Name :-RWD,Works Divisin,Dalsinghsarai

1	Name of the Road	NH-28 Shankar Chwok Se Chapta Nikaspur Dalit Basti Tak		
2	Batch No.	RM/SA/DAL/19/0010		
3	Project ID	10105118		
4	Total Length of Road (in Km)	6.8		
5	Length of Road to Meet Required Service Level [Completed length] (in Km) [1]	6.8		
6	No. of Total Quarter (ie 3 Months as a in 5 years	20		
7	Ordinary Maintenance Cost as per Schedule [Agreement Amount for Maintenance] (in Lakh)	6.20447		
8	Quarterly Payment :3/20 of Ordinary Maintenance Cost as per Schedule (in Lakh) [2]	3.03751		
Compliance Criteria	Standard Job Description	Non- Compliance		Reduction Payment [6]=[3]/[1]*[2]*[4]
		Length Non- compliant [3]	Weighted Value for Payment Reduction (%) [4]	
I	PAVED ROADS		60%	0
II	SHOULDERS AND		10%	0
III	CROSS DRAINAGE		15%	0
IV	SIGNAGE AND ROAD		10%	0
V	VEGETATION		5%	0
TOTAL PAYMENT REDUCTION FOR THE QUARTER (in Lakh) [5]				0
TO BE PAID FOR THE QUARTER / DEMAND (in Lakh) [6]				3.03751

Date of inspection by E/I or his agent

Prepared by Contractor's Self Control Unit

Name and Designation of person inspecting road

Date


Signature of person inspecting road

(Signature)

Certify by E/I [signature] Date:-

Executive Engineer
Rural works Department
Works Division,Dalsinghsarai

Name of Customer: SONA INFRACON PRIVATE LIMITED, Machine no: 19190, Road: NH-28 Shankar Chowk Se Chapla Nikaspur Dalit Basti Tak, Date: 13/08/22, Section No: 24, Equation: $Y=0.909X+125.0$



Handwritten signature
14/08/22
SE

Handwritten signature
14/08/22
SE

Handwritten signature
14/08/22
E.E.

Name of the work: NH-28 Shankar Chwok Se Chaptla Nilkaspur Dalit Basti Tak

Date	Time	Test No	Distance (meter)	Total Distance (meter)	BUMP (cm)	Speed(Km/Hr)	UI(mm/Km)	Corrected UI (mm/Km)	IRI	Status	Latitude	Direction	Longitude	Direction1	Remarks
13/08/22	16:50:34	24	100	100	11.0 cm	10.2 Km/Hr	1100.0 mm/Km	1124.9	1.678	Good	25.73256	N	85.795252	E	Normal
13/08/22	16:51:10	24	100	200	33.0 cm	10.0 Km/Hr	3300.0 mm/Km	3124.7	3.178	Good	25.73226	N	85.796127	E	Normal
13/08/22	16:51:31	24	100	300	32.0 cm	17.1 Km/Hr	3200.0 mm/Km	3033.8	3.069	Good	25.73195	N	85.79707	E	Normal
13/08/22	16:51:53	24	100	400	33.0 cm	16.3 Km/Hr	3300.0 mm/Km	3124.7	3.178	Good	25.73207	N	85.798097	E	Normal
13/08/22	16:52:19	24	100	500	24.0 cm	13.9 Km/Hr	2400.0 mm/Km	2306.6	3.186	Good	25.73244	N	85.798737	E	Normal
13/08/22	16:53:03	24	100	600	35.0 cm	18.1 Km/Hr	3500.0 mm/Km	3306.5	3.394	Good	25.73222	N	85.799763	E	Normal
13/08/22	16:53:26	24	100	700	34.0 cm	15.7 Km/Hr	3400.0 mm/Km	3215.6	3.286	Good	25.73183	N	85.800605	E	Normal
13/08/22	16:53:46	24	100	800	33.0 cm	18.0 Km/Hr	3300.0 mm/Km	3124.7	3.178	Good	25.73136	N	85.80138	E	Normal
13/08/22	16:54:09	24	100	900	34.0 cm	15.5 Km/Hr	3400.0 mm/Km	3215.6	3.286	Good	25.73114	N	85.80234	E	Normal
13/08/22	16:54:34	24	100	1000	36.0 cm	14.6 Km/Hr	3600.0 mm/Km	3397.4	3.502	Good	25.7308	N	85.803248	E	Normal
13/08/22	16:55:36	24	100	1100	38.0 cm	15.5 Km/Hr	3800.0 mm/Km	3579.2	3.716	Good	25.73054	N	85.80414	E	Normal
13/08/22	16:56:09	24	100	1200	33.0 cm	11.2 Km/Hr	3300.0 mm/Km	3124.7	3.178	Good	25.73029	N	85.80507	E	Normal
13/08/22	16:56:35	24	100	1300	20.0 cm	13.8 Km/Hr	2000.0 mm/Km	1943	2.734	Good	25.72994	N	85.80601	E	Normal
13/08/22	16:57:03	24	100	1400	30.0 cm	12.7 Km/Hr	3000.0 mm/Km	2852	3.851	Good	25.72912	N	85.806328	E	Normal
13/08/22	16:57:36	24	100	1500	22.0 cm	10.9 Km/Hr	2200.0 mm/Km	2124.8	2.961	Good	25.72876	N	85.80675	E	Normal
13/08/22	16:58:17	24	100	1600	29.0 cm	19.0 Km/Hr	2900.0 mm/Km	2761.1	3.741	Good	25.72966	N	85.80632	E	Normal
13/08/22	16:58:44	24	100	1700	22.0 cm	12.9 Km/Hr	2200.0 mm/Km	2124.8	2.961	Good	25.72969	N	85.80771	E	Normal
13/08/22	17:02:32	24	100	1800	33.0 cm	11.5 Km/Hr	3300.0 mm/Km	3124.7	3.178	Good	25.72954	N	85.809562	E	Normal
13/08/22	17:03:41	24	100	1900	37.0 cm	19.8 Km/Hr	3700.0 mm/Km	3488.3	3.609	Good	25.7294	N	85.810505	E	Normal
13/08/22	17:04:43	24	100	2000	31.0 cm	15.7 Km/Hr	3100.0 mm/Km	2942.9	3.96	Good	25.72926	N	85.811515	E	Normal
13/08/22	17:05:40	24	100	2100	38.0 cm	16.5 Km/Hr	3800.0 mm/Km	3579.2	3.716	Good	25.7292	N	85.81244	E	Normal
13/08/22	17:06:16	24	100	2200	31.0 cm	19.6 Km/Hr	3100.0 mm/Km	2942.9	3.96	Good	25.72896	N	85.81342	E	Normal
13/08/22	17:10:43	24	100	2300	36.0 cm	11.3 Km/Hr	3600.0 mm/Km	3397.4	3.502	Good	25.72878	N	85.814393	E	Normal
13/08/22	17:11:21	24	100	2400	38.0 cm	19.4 Km/Hr	3800.0 mm/Km	3579.2	3.716	Good	25.72857	N	85.815453	E	Normal
13/08/22	17:12:22	24	100	2500	32.0 cm	16.9 Km/Hr	3200.0 mm/Km	3033.8	3.069	Good	25.72835	N	85.816463	E	Normal
13/08/22	17:13:32	24	100	2600	34.0 cm	17.2 Km/Hr	3400.0 mm/Km	3215.6	3.286	Good	25.72915	N	85.816885	E	Normal
13/08/22	17:14:23	24	100	2700	37.0 cm	15.4 Km/Hr	3700.0 mm/Km	3488.3	3.609	Good	25.72998	N	85.817272	E	Normal
13/08/22	17:15:11	24	100	2800	31.0 cm	13.1 Km/Hr	3100.0 mm/Km	2942.9	3.96	Good	25.73054	N	85.816918	E	Normal
13/08/22	17:16:19	24	100	2900	33.0 cm	14.6 Km/Hr	3300.0 mm/Km	3124.7	3.178	Good	25.73064	N	85.815942	E	Normal
13/08/22	17:17:16	24	100	3000	39.0 cm	11.8 Km/Hr	3900.0 mm/Km	3670.1	3.823	Good	25.7309	N	85.814965	E	Normal
13/08/22	17:18:14	24	100	3100	29.0 cm	12.9 Km/Hr	2900.0 mm/Km	2761.1	3.741	Good	25.7311	N	85.81404	E	Normal
13/08/22	17:19:18	24	100	3200	33.0 cm	16.5 Km/Hr	3300.0 mm/Km	3124.7	3.178	Good	25.7313	N	85.812962	E	Normal
13/08/22	17:20:10	24	100	3300	29.0 cm	16.9 Km/Hr	2900.0 mm/Km	2761.1	3.741	Good	25.73201	N	85.812912	E	Normal

13/08/22	17:21:15	24	100	3400	32.0 cm	12.2 Km/Hr	3200.0 mm/Km	3033.8	3.069	Good	25.73281	N	85.81345	E	Normal
13/08/22	17:22:21	24	100	3500	29.0 cm	10.2 Km/Hr	2900.0 mm/Km	2761.1	3.741	Good	25.73367	N	85.81367	E	Normal
13/08/22	17:23:25	24	100	3600	19.0 cm	13.9 Km/Hr	1900.0 mm/Km	125	0.236	Good	25.73442	N	85.814073	E	Normal
13/08/22	17:24:29	24	100	3700	37.0 cm	16.5 Km/Hr	3700.0 mm/Km	3488.3	3.609	Good	25.73526	N	85.814595	E	Normal
13/08/22	17:25:32	24	100	3800	39.0 cm	13.7 Km/Hr	3900.0 mm/Km	3670.1	3.823	Good	25.73596	N	85.815218	E	Normal
13/08/22	17:26:12	24	100	3900	29.0 cm	11.1 Km/Hr	2900.0 mm/Km	2761.1	3.741	Good	25.73661	N	85.815757	E	Normal
13/08/22	17:27:11	24	100	4000	19.0 cm	10.9 Km/Hr	1900.0 mm/Km	1852.1	2.619	Good	25.73747	N	85.815807	E	Normal
13/08/22	17:28:14	24	100	4100	33.0 cm	14.2 Km/Hr	3300.0 mm/Km	125	0.236	Good	25.73832	N	85.816127	E	Normal
13/08/22	17:29:19	24	100	4200	39.0 cm	16.1 Km/Hr	3900.0 mm/Km	3670.1	3.823	Good	25.73904	N	85.816648	E	Normal
13/08/22	17:30:16	24	100	4300	29.0 cm	12.1 Km/Hr	2900.0 mm/Km	2761.1	3.741	Good	25.7394	N	85.817473	E	Normal
13/08/22	17:31:12	24	100	4400	31.0 cm	11.9 Km/Hr	3100.0 mm/Km	2942.9	3.96	Good	25.74027	N	85.817727	E	Normal
13/08/22	17:32:17	24	100	4500	33.0 cm	13.4 Km/Hr	3300.0 mm/Km	3124.7	3.178	Good	25.74122	N	85.817137	E	Normal
13/08/22	17:33:19	24	100	4600	22.0 cm	10.9 Km/Hr	2200.0 mm/Km	2124.8	2.961	Good	25.74191	N	85.81771	E	Normal
13/08/22	17:34:14	24	100	4700	29.0 cm	14.6 Km/Hr	2900.0 mm/Km	2761.1	3.741	Good	25.74232	N	85.81511	E	Normal
13/08/22	17:35:15	24	100	4800	39.0 cm	16.5 Km/Hr	3900.0 mm/Km	3670.1	3.823	Good	25.74273	N	85.81507	E	Normal
13/08/22	17:36:22	24	100	4900	37.0 cm	14.9 Km/Hr	3700.0 mm/Km	3488.3	3.609	Good	25.7435	N	85.814595	E	Normal
13/08/22	17:37:21	24	100	5000	19.0 cm	12.3 Km/Hr	1900.0 mm/Km	1852.1	2.619	Good	25.74436	N	85.81409	E	Normal
13/08/22	17:38:32	24	100	5100	29.0 cm	9.9 Km/Hr	2900.0 mm/Km	2761.1	3.741	Good	25.74525	N	85.81457	E	Normal
13/08/22	17:39:23	24	100	5200	39.0 cm	17.0 Km/Hr	1700.0 mm/Km	1670.3	2.388	Good	25.74614	N	85.814242	E	Normal
13/08/22	17:40:25	24	100	5300	19.0 cm	13.1 Km/Hr	1900.0 mm/Km	1852.1	2.619	Good	25.74726	N	85.814308	E	Normal
13/08/22	17:41:29	24	100	5400	32.0 cm	12.9 Km/Hr	3200.0 mm/Km	3033.8	3.069	Good	25.74816	N	85.814595	E	Normal
13/08/22	17:42:22	24	100	5500	28.0 cm	11.5 Km/Hr	2800.0 mm/Km	2670.2	3.631	Good	25.74906	N	85.814813	E	Normal
13/08/22	17:43:26	24	100	5600	39.0 cm	16.2 Km/Hr	3900.0 mm/Km	3670.1	3.823	Good	25.74991	N	85.815202	E	Normal
13/08/22	17:44:25	24	100	5700	26.0 cm	11.9 Km/Hr	2600.0 mm/Km	2488.4	3.409	Good	25.75084	N	85.81579	E	Normal
13/08/22	17:45:27	24	100	5800	36.0 cm	12.0 Km/Hr	3600.0 mm/Km	3397.4	3.502	Good	25.75088	N	85.81677	E	Normal
13/08/22	17:46:12	24	100	5900	37.0 cm	12.9 Km/Hr	3700.0 mm/Km	3488.3	3.609	Good	25.75107	N	85.817845	E	Normal
13/08/22	17:47:10	24	100	6000	39.0 cm	13.4 Km/Hr	3900.0 mm/Km	3670.1	3.823	Good	25.75147	N	85.819443	E	Normal
13/08/22	17:48:11	24	100	6100	33.0 cm	11.9 Km/Hr	3300.0 mm/Km	3124.7	3.178	Good	25.75084	N	85.815823	E	Normal
13/08/22	17:49:17	24	100	6200	29.0 cm	10.1 Km/Hr	2900.0 mm/Km	2761.1	3.741	Good	25.75754	N	85.816195	E	Normal
13/08/22	17:51:22	24	100	6300	31.0 cm	11.9 Km/Hr	3100.0 mm/Km	2942.9	3.96	Good	25.76001	N	85.81342	E	Normal
13/08/22	17:52:14	24	100	6400	39.0 cm	16.2 Km/Hr	3900.0 mm/Km	3670.1	3.823	Good	25.76042	N	85.812845	E	Normal
13/08/22	17:53:32	24	100	6500	36.0 cm	11.9 Km/Hr	3600.0 mm/Km	3397.4	3.502	Good	25.76053	N	85.8118	E	Normal
13/08/22	17:54:42	24	100	6600	29.0 cm	13.2 Km/Hr	2900.0 mm/Km	2761.1	3.741	Good	25.76137	N	85.81168	E	Normal
13/08/22	17:55:32	24	100	6700	19.0 cm	10.9 Km/Hr	1900.0 mm/Km	1852.1	2.619	Good	25.76157	N	85.810723	E	Normal
13/08/22	17:55:32	24	100	6800	9.0 cm	6.9 Km/Hr	900.0 mm/Km	943.1	1.434	Good	25.76187	N	85.809848	E	Normal

11.18 min
 85.81168
 85.810723
 85.809848
 Machine ID
 IRI Value
 19190
 3816