

कार्यपालक अभियंता का कार्यालय,
ग्रामीण कार्य विभाग, कार्य प्रमण्डल, आरा ।

पत्रांक.....1949376

आरा, दिनांक.....14/12/2022

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, आरा ।

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव
ग्रामीण कार्य विभाग
बिहार, पटना ।

विषय:- बिहार ग्रामीण पथ अनुरक्षण नीति-2018 के तहत पथों की
अधियाचना के संबंध में ।


महाशय,

उपर्युक्त विषय के संबंध में सूचित करना है कि बिहार ग्रामीण पथ अनुरक्षण
नीति-2018 के तहत पथों के भुगतान हेतु संलग्न विवरणी के अनुसार रु0-75.79980
लाख रु0 की आवश्यकता है ।

अतः अनुरोध है कि यथाशीघ्र उक्त राशि को आवंटित करने की कृपा
की जाय, जिससे संवेदक का भुगतान किया जा सकें ।

अनु0 यथोक्त ।

विश्वासभाजन


कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, आरा ।


13/12/2022

1. Signed Hard Copy and Soft Copy (in excel) of recorded IRI is enclosed.
2. Up-to date Physical Progress has been uploaded in MTS.

Executive Engineer
Rural Works Department
Works Division, Aiz

FORM GFR 19-A
(See Government of India's Decision (1) below Rule-150)
Form of utilisation Certification up to month of Dec, 2022
MR Maintenance Policy- 2018
R.W.D. Works Division-Ara (Bhojpur)

Sl. No.	Name of Scheme	Sanction No & Date with Amount (In Rs. Lacs)	Amount Received (In Rs. Lacs)	Particulars
1.	Construction of Rural Road under MR Maint. Policy- 2018	Letter No-53 we Date- 12.12.2022	589786250.00	Certified that out of Rs. 589786250.00 Lacs of grant in aid received during the Year 2022-23 in favour of Executive Engineer, RWD Bihar R.W.D. Ara. A sum of Rs. 535868149.00 Lacs has been utilized for the purpose of MR Maint. Policy- 2018 Schemes as given in the margin for which it was sanctioned and that the balance of Rs. 53918101.00 Lacs remaining unutilized at the end of the period under.
		Total	589786250.00	


2. Certified that I have satisfied myself that the conditions on which the grants-in aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.


Kind of Checks exercised:-

- I. Works have been supervised by Executive Engineer/ Superintending Engineer.
- II. Periodical inspection has been conducted by Executive Engineer/Superintending Engineer.
- III. Construction materials have been tested.
- IV. Measurements have been recorded in the MBS and test check conducted by the Assistant Engineer/Executive Engineer.
- V. All other codal formalities have been observed.

3. Physical progress achieved:

- i. Construction of Road Works.
- ii. Construction of CD Works.


D.A.O.
Rural Works Department
Works Div-Ara


Executive Engineer
Rural Works Department
Works Div. Ara

ROAD NAME-1042-102 TO ITHARIYA

CONTRACTOR NAME-RITIK KUMAR SINGH

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR	IRI CATEGORY	Latitude	Longitude	Event	
9/12/22	7:31:29	73	0.1	300	0	2800	2996 G	25.659731	84.649247	Normal	$Y = 0 * X^2 + 0.969 * X + 74.60$
9/12/22	7:32:4	73	0.1	290	10.1	2900	2884 G	25.659293	84.649665	Normal	$X = 2800$
9/12/22	7:32:40	73	0.1	310	10.1	3100	3078 G	25.658402	84.649913	Normal	$Y = 2787$
9/12/22	7:33:0	73	0.1	280	20.2	2700	2842 G	25.657961	84.650292	Curve	
9/12/22	7:33:15	73	0.1	280	20.2	3100	3254 G	25.656984	84.650887	Normal	(R) RURAL ROAD
9/12/22	7:33:15	73	0.1	300	20.2	3000	2981 G	25.656175	84.651316	Normal	Good
9/12/22	7:34:40	73	0.1	270	10.1	3300	3456 G	25.655586	84.651309	Normal	Average
9/12/22	7:35:0	73	0.1	290	20.2	2900	2884 G	25.654493	84.651616	Normal	Poor
9/12/22	7:35:15	73	0.1	270	20.2	3100	3200 G	25.653653	84.651693	Curve	<4000
9/12/22	7:35:15	73	0.1	250	20.2	2500	2497 G	25.652847	84.65173	Normal	4001-5000
9/12/22	7:36:0	73	0.1	290	10.1	2900	2884 G	25.651867	84.65166	Normal	>5001
9/12/22	7:36:40	73	0.1	270	10.1	2600	2593 G	25.651234	84.651634	Normal	
9/12/22	7:37:0	73	0.1	280	20.2	3500	3657 G	25.650401	84.651562	Normal	
9/12/22	7:37:15	73	0.1	300	20.2	3000	2981 G	25.649635	84.648671	Normal	
9/12/22	7:37:15	73	0.1	250	20.2	2400	2400 G	25.64808	84.653255	Normal	
9/12/22	7:38:0	73	0.1	260	10.1	2600	2593 G	25.647183	84.653407	Normal	
9/12/22	7:38:40	73	0.1	280	10.1	3300	3457 G	25.646215	84.653586	Curve	
9/12/22	7:39:0	73	0.1	280	20.2	3400	3541 G	25.645568	84.653654	Normal	
9/12/22	7:39:15	73	0.1	320	20.2	3200	3175 G	25.644797	84.653767	Normal	
9/12/22	7:39:15	73	0.1	340	20.2	3000	2981 G	25.643968	84.653627	Normal	
9/12/22	7:40:0	73	0.1	300	10.1	3000	2981 G	25.643172	84.653179	Normal	
9/12/22	7:40:0	73	0.1	280	20.2	2800	2787 G	25.643173	84.65318	Normal	
		TOTAL		66102							
		AVERAGE		3004							

Sumed
12/12/2022
DE


Sumed
12/12/22
A.C

Sumed
12/12/22
A.C

Sumed
12/12/22
A.C



File : C:\Users\BRRDA 52\Desktop\rambabu\21111016.xls, Section No. : 73, Eqn : $Y = 0 * X^2 + 0.969 * X + 74.60$
Name of Customer : Ritik kumar singh, Name of Work/ Road : L042-T02 TO ITHARIYA, Lab Job number : 73



Handwritten signature
12/12/2022

Handwritten signature
19.12.22


Handwritten signature
13/11/22


प्रमाण पत्र

शीर्ष:- 3054 एम0आर0 (बिहार ग्रामीण पथ अनुरक्षण 2018)

योजना:- L042-T02 TO Ithariya (VR42)

1. मापी पुस्त पर इस आशय का प्रमाण पत्र दर्ज है कि कार्य गुणवत्ता पूर्ण कराया गया है।
2. कराये गये कार्यों के सभी अवयवों के अवयववार 100 प्रतिशत कार्य का दर्ज मापी का सत्यापन कनीय अभियंता, 50 प्रतिशत मापी का सत्यापन सहायक अभियंता एवं 10 प्रतिशत मापी का सत्यापन कार्यपालक अभियंता द्वारा किया गया है।


12/12/2022
कनीय अभियंता
कार्य प्रशाखा, बड़हरा


13/12/22
सहायक अभियंता
कार्य अवर प्रमंडल, बड़हरा


13/12/22
कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, आरा