

Inspection Report For Flood Damage Work

Date: 16/12/2021

1. Name of PUs - E.E. R.W.D (W) Division Nargachhiye.
2. Name of Block/Road (Rangrochowk) LOAI-NH-31 to Sankha Chapar village (V.P. No.)

A. For Road

1. Damage Location/Chainage 0-33, to 1.00 km
2. Damage length — 0.295 km.
3. Nature of Damage — flank cutting
4. Detail of Restoration Works 0.295 km
 - (i) Material being used in Restoration Works: EC bag & local sand
 - (ii) Equipment's/ Tools Being used in Restoration Works:
 - (iii) Procedure Taken up in Restoration Works:
 - (iv) Restored Length:

B. For Bridge — NA


1. Damage Location/Chainage
2. Damage length
3. Nature of Damage
4. Detail of Restoration Works
 - (i) Material being used in Restoration Works:
 - (ii) Equipment's/ Tools Being used in Restoration Works:
 - (iii) Procedure Taken up in Restoration Works:
 - (iv) Restored Length:


C. Requirement Of New CD/Bridges


- (i) Name of Road:
- (ii) Location/ Chainage
- (iii) Type of CD Work/Length required — NA -

Notes:-

- Upload one Photograph of damaged portion if available
- Attach minimum Two Photograph (during restoration & after restoration) Photographs should be Geotags and at Least one Photo be captured in selfie mode.


Signature of JE/AF/EE


16/12/21
A.E.
कार्यपालिक अभियन्ता
ग्रामीण कार्य विभाग
कार्य प्रमण्डल नवगछिया


Signature
(Name of Inspector)

_____ to Sadhu abpar village (R.A.

Naygachhi-
Rangachowk

.....DIVISION •

.....SUB DIVISION

MEASUREMENT BOOK

657

657 में सजीव कुटिल धुवा 100/-
 (कल) के अति है। अणु मापी प्रका
 सी वरिष्ठ प्रसा, सहायक अभियंता, कार्य
 आपा प्रसा, रंगराजपुर के नाम
 Emergent repair & reclamation
 of rural roads affected by
 heavy rain/flood का कार्य है।
 निर्गत किया जाता है।

R. W. D. Naugachia
 Executive Engineer
 R. W. D. Naugachia
 11/9/2024

Schedule XLV Form No. 134

Naugachia DIVISION

Rangrajpur SUB-DIVISION

MEASUREMENT BOOK

NO-657

Name of Office.....

Date of first entry.....

Date of last entry.....

Sch. XLV-Form No. 134

| Particulars | Details of actual measurement | | | | C or D |
|-------------|-------------------------------|-------|------|------|--------------------------|
| | No. | L. | B. | D. | |
| CH: 35-49 | 1x | 30m | 1.50 | 2.60 | 70 = 43.05m ² |
| | 1x | 30m | 1.50 | 2.60 | 70 = 43.05m ² |
| | 1x | 30m | 1.50 | 2.60 | 70 = 43.05m ² |
| | 1x | 30m | 1.50 | 2.60 | 70 = 43.05m ² |
| | 1x | 30m | 1.50 | 2.60 | 70 = 43.05m ² |
| | 1x | 10m | 1.50 | 2.60 | 70 = 14.35 |
| CH: 440-462 | 1x | 22.00 | 1.50 | 2.60 | 70 = 31.52m ² |
| 462-466 | 1x | 4.00 | 1.50 | 2.60 | 70 = 6.24 |
| 483-486 | 4x | 3.00 | 1.20 | 2.50 | 75 = 4.39 |
| 490-535 | 1x | 30.00 | 1.40 | 2.50 | 75 = 48.25 |
| | 1x | 15.00 | 1.40 | 2.50 | 75 = 21.93 |
| 1000-1010 | 1x | 10.00 | 1.55 | 2.60 | 70 = 16.64 |

| | | | | | |
|-------------|----|------|------|------|----------------------|
| CH: 800-810 | 2x | 5.00 | 1.50 | 2.45 | 70 = 15.44 |
| 992-1000 | 2x | 4.00 | 1.20 | 2.50 | 70 = 10.36 |
| | | | | | 429.55m ² |

27/10/2021
JE.

27/10/21
MS