

**कार्यपालक अभियंता का कार्यालय,
ग्रामीण कार्य विभाग, कार्य प्रमंडल, कटिहार।**

पत्रांक :- 198

/कटिहार, दिनांक- 03-2-2022

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, कटिहार।

सेवा में,

अपर-मुख्य-कार्यपालक-पदाधिकारी,
BRRDA, 3री मंजिल, भूमि विकास बैंक भवन,
बिहार, पटना।

विषय :- शीर्ष New Maintenance Policy-2018 योजनान्तर्गत निर्माण हेतु आवंटन की
अधियाचना के संबंध में।

महाशय,

उपर्युक्त विषय के संबंध में कहना है कि शीर्ष New Maintenance Policy-2018
योजनान्तर्गत ग्रा0का0वि0, कार्य प्रमंडल, कटिहार द्वारा विहित प्रपत्र में अधियाचना तैयार कर आपके
अग्रेतर कार्रवाई हेतु समर्पित की जाती है।

अनु0:-यथोक्त।

विश्वासभाजन,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, कटिहार।

ज्ञापांक:- 198

/कटिहार, दिनांक:- 03-02-2022

प्रतिलिपि:- नोडल पदाधिकारी, 3054 MR, ग्रामीण कार्य विभाग, बिहार, पटना को सूचनार्थ एवं
आवश्यक कार्रवाई हेतु समर्पित।

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, कटिहार।

RWD, Works Division, Katihar

Requisition Format for Scheme Head - MR (3054) Under Bihar Rural Road maintenance Policy 2018 (Initial Rectification and Surface Renewal)

Name of Division : Katihar

Sl. No.	Package no.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative Approval (AA)		Agreement Amount (in Lac)		Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in percentage	Previous Total Allotted Amount (in Lac)	up to date expenditure as per MIS (in Lac)	Requisition Against work done (in lac)	Remarks
					Length (in Km)	Amount (in Lac)	Initial Rectification with Surface Renewal (in lac)	5 years Routine Maintenance (in lac)										
1	MIR-N/19-20 Katihar/07	Chandwa Rupasur Upto Ramaillee Panchayat Bhawan	21105602015	1847/24.06.19	3.200	118.55330	74.37504	35.09263	06MBD/20-21, 08.08.2020	07.05.2021	-	2096.75	25mm	5.1%	0.00000	0.00000	73.92460	Surface Complete
Total															0.00000	0.00000	73.92460	-

[Signature]
Executive Engineer
RWD, Works Division, Katihar

(See Government of India's Decision (1) below Rule-150)
Form of Utilisation Certificate upto the month of Jan, 2022

New Maintenance Policy-2018

2. Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

- i. Works have been supervised by Executive Engineer/Superintending Engineer.
- ii. Periodical inspection has been conducted by Executive Engineer/Superintending Engineer.
- iii. Construction materials have been tested.
- iv. Measurements have been recorded in the MBs and test check conducted by the Assistant.
- v. All other codal formalities have been observed.

- i. Construction of Road Works.
- ii. Construction of CD Works.

- i. Work has been done as per specification and with quality.
- ii. Work done measurement entered in MB has been verified 100 % by JE, 50% by AE and 10% by EE.

Executive Engineer
RWD (W) Division, Katihar.

2-2-2022

Lab Job number :19

Date :09-01-2022

Name of Customer :Chandwa Rupaspur Upto Ramailee Panchayat Bhawan

Name of Work/ Road :Bharat Bushan

Sr.no	Location of test (in km)	Corrected U.I value (mm/km)	Road category
1	0.100	3175	G
2	0.200	1721	G
3	0.300	1818	G
4	0.400	3466	G
5	0.500	2593	G
6	0.600	2400	G
7	0.700	2593	G
8	0.800	1818	G
9	0.900	2303	G
10	1.000	2109	G
11	1.100	2690	G
12	1.200	2012	G
13	1.300	2109	G
14	1.400	1624	G
15	1.500	1624	G
16	1.600	2206	G
17	1.700	2012	G
18	1.800	1721	G
19	1.900	2497	G
20	2.000	1915	G
21	2.100	2206	G
22	2.200	1818	G
23	2.300	2109	G
24	2.400	1818	G
25	2.500	1818	G
26	2.600	1818	G
27	2.700	2109	G
28	2.800	2109	G
29	2.900	1915	G
30	3.000	1431	G
31	3.100	1624	G
32	3.200	1915	G
Average IRI Value		2096.75	

Zunal
10/01/2022
J.E

10.01.2022
A.E

Executive Engineer
R.W.D. (W) Division
Katiha

Lab Job number :19

Date :09-01-2022

Name of Customer :Chandwa Rupaspur Upto Ramailee Panchayat Bhawan

Name of Work/ Road :Bharat Bushan

Date	Time	Section No.	Length In km	Bumps In mm	Speed Rate	OR mm/km	IRI mm/km	CATEGORY ROAD	Latitude	Longitude	Event
9/1/22	10:51:8	19	0.100	320	0	3200	3175	G	25.652705	87.494578	Normal
9/1/22	10:51:44	19	0.100	170	10.1	1700	1721	G	25.652173	87.493820	Curve
9/1/22	10:52:0	19	0.100	180	10.1	1800	1818	G	25.651470	87.493502	Normal
9/1/22	10:52:19	19	0.100	350	20.2	3500	3466	G	25.651507	87.492542	Normal
9/1/22	10:52:19	19	0.100	260	20.2	2600	2593	G	25.651620	87.491565	Normal
9/1/22	10:52:54	19	0.100	240	20.2	2400	2400	G	25.651800	87.490505	Normal
9/1/22	10:53:0	19	0.100	260	20.2	2600	2593	G	25.651780	87.489662	Curve
9/1/22	10:53:0	19	0.100	180	20.2	1800	1818	G	25.650870	87.489443	Culvert
9/1/22	10:53:29	19	0.100	230	20.2	2300	2303	G	25.650032	87.489175	Normal
9/1/22	10:53:29	19	0.100	210	20.2	2100	2109	G	25.649150	87.488905	Curve
9/1/22	10:54:5	19	0.100	270	10.1	2700	2690	G	25.649142	87.487928	Normal
9/1/22	10:54:5	19	0.100	200	10.1	2000	2012	G	25.649220	87.486952	Normal
9/1/22	10:54:40	19	0.100	210	20.2	2100	2109	G	25.648862	87.486110	Curve
9/1/22	10:55:0	19	0.100	160	30.3	1600	1624	G	25.648803	87.485150	Normal
9/1/22	10:55:15	19	0.100	160	10.1	1600	1624	G	25.648982	87.484090	Normal
9/1/22	10:55:51	19	0.100	220	10.1	2200	2206	G	25.649147	87.483097	Normal
9/1/22	10:56:0	19	0.100	200	10.1	2000	2012	G	25.649723	87.482390	Curve
9/1/22	10:56:26	19	0.100	170	20.2	1700	1721	G	25.650507	87.482103	Curve
9/1/22	10:56:26	19	0.100	250	20.2	2500	2497	G	25.651387	87.481852	Curve
9/1/22	10:57:1	19	0.100	190	20.2	1900	1915	G	25.651697	87.480975	Normal
9/1/22	10:57:1	19	0.100	220	30.3	2200	2206	G	25.651975	87.479948	Normal
9/1/22	10:57:1	19	0.100	180	20.2	1800	1818	G	25.651803	87.479140	Curve
9/1/22	10:57:36	19	0.100	210	30.3	2100	2109	G	25.651875	87.478215	Normal
9/1/22	10:57:36	19	0.100	180	30.3	1800	1818	G	25.651982	87.477120	Normal
9/1/22	10:57:36	19	0.100	180	40.4	1800	1818	G	25.652045	87.476110	Culvert
9/1/22	10:58:0	19	0.100	180	40.4	1800	1818	G	25.651975	87.475130	Culvert
9/1/22	10:58:12	19	0.100	210	40.4	2100	2109	G	25.651770	87.474242	Normal
9/1/22	10:58:12	19	0.100	210	30.3	2100	2109	G	25.651480	87.473248	Normal
9/1/22	10:58:12	19	0.100	190	40.4	1900	1915	G	25.651075	87.472305	Normal
9/1/22	10:58:12	19	0.100	140	30.3	1400	1431	G	25.650513	87.471632	Normal
9/1/22	10:58:47	19	0.100	160	30.3	1600	1624	G	25.650180	87.470638	Normal
9/1/22	10:59:0	19	0.100	190	20.2	1900	1915	G	25.650065	87.469730	Normal

$$Y = 0 \cdot X^2 + 0.969 \cdot X + 74.60$$

$$X = 1900$$

$$Y = 1915$$


(R) RURAL ROAD
Good <4000
Average 4001-5000
Poor >5001

10/01/2022
A-E

10/01/2022
A-E

Executive Engineer
R.W.D. (W) Division
Kathia

File: C:\RAM KUMAR\MISC Files\Bump integrator\Koriha\Chandwa Rupushpur\09011255.Xls. Section No.: 19. Eqn:
 Name of Customer: Chandwa Rupaspur Upto Ramaile Panchayat Bhawan. Name of Work/ Road: Bharat Buzhan.



[Signature]
 10/10/2022
 P.E

[Signature]
 10/10/2022
 P.E

[Signature]
 Executive Engineer
 R.W.D. (W) Division
 Katihar

BHARAT BHUSHAN

CHANDWA RUPASPUR 3054/MR
PANCHAYAT BHAWAN, UP-TO RAMAILEE

Measurement Book

Schedule XLV-Form No. 134

R.W.D. KATHAR — DIVISION

KORHA — SUB-DIVISION
(NO-2026)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
let on Ale Bill					
Name of work: Construction and Maintenance					
of Road from Chandwar					
Rupashpur To Remailp					
panchayat Bhaurin -					
Name of Agency: Bharat Bhushan					
burner College Road burner					
Agreement No - 96 MBD					
8/08/2020-2021					
Work order - 8/08/2020					
Work completion -					
Abstract of cost					
Date of Entry 10/01/2022					

1/22	Clearing and grubbing				
	road land including				
	0.640 Hrc Qty vide TMB p.2 - Item (1)				
	@ 49496.70/Hrc	316	78	=00	
2/22	priming and fixing				
	informative sign board				
	2.0 Nos Qty vide TMB p.2 Item (2)				
	@ 9235.27 each	18	471	=00	
3/26	Earthwork in excavation				
	for foundation structure				
	89.39 M ³ Qty vide TMB p.2 Item (3)				
	@ 260.59 M ³	23	294	=00	
4/27	providing pcc M15				
	13.77 M ³ Qty vide TMB p.2 Item (4)				
	@ 5039.40 M ³	69	324	=00	
	Continuation				
	CLOS	14	2767	=00	

Scanned with CamScanner