

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, समस्तीपुर

पत्रांक 265 दिनांक 14.02.22

प्रेषक:- कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, समस्तीपुर।



सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव
ग्रामीण कार्य विभाग, बिहार, पटना।

विषय:- शीर्ष New Maintenance Policy-2018 मद में आवंटन उपलब्ध कराने के संबंध में।
महाशय,
उपर्युक्त विषयक शीर्ष New Maintenance Policy-2018 मद अन्तर्गत विहित प्रपत्र में
अधियाचना पत्र संलग्न कर भेजा जा रहा है।

अतः अनुरोध है कि संलग्न अधियाचना पत्र के अनुसार आवंटन उपलब्ध कराने की कृपा
की जाये।
अनु०-यथोक्त।

विश्वासभाजन


कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, समस्तीपुर

14.2.22

FROM GFR 19-A

(See Government of India's Division (I) below Rule- 150)

Form of Utilization Certificate upto 13.02.2022

PIU- E.E., R.W.D. Works Division, Samastipur

S.N.	Name of Scheme	Sanction No.& Date	Amount Received	Particulars
1	Construction of Rural Road under New Maintenance Policy-2018	Secretary cum Empowered Officer BRRDA Bihar Patna vide upto L.I. no.-28 dt. 27.01.2022	260404273.00	Certified that out of Rs.260404273.00 received upto 13.02.2022 in favour of Executive Engineer R.W.D. Works Division Samastipur a sum of Rs.259961487.00 has been utilized for the purpose of New Maintenance Policy-2018 Schemes as given in the margine for which it was sanctioned and that the balance of Rs. 442786.00 remaining unutilized at the end of period under report.
			26,04,04,273.00	

2. Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have been duly fulfilled are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for the which it was sanctioned.

Kind of Checks exercised:-

- i Works have been supervised by Executive/Superintending engineer.
- ii Periodical inspection has been conducted by Executive/Superintending engineer.
- iii Construction materials have been tested.
- iv Measurements have been recorded in the MB's and test check conducted by Assistant Engineer/Executive
- v All other codal formalities have been observed.

3 Physical Progress achieved:-

- i Construction of Road work.
- ii Construction of CD works.

[Signature]
14.2.22
Executive Engineer
Works Division Samastipur
Rural Works Department

[Signature]
14.2.22

Requisition Format for scheme Head : MR(3054) Under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

RWD, Works Division : Samastipur		Project ID as per MES	Name of Road	Administrative Approval (AA) Letter No & Date	Administrative		Agreement Amount		Agreement No & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (In million)	Thickness of Bitumen Layer (In MM)	Value of Bitumen Content in Percentage	Previous Total Allocated Amount (In Lakh)	Up to date Expenditure as per MES (In Lakh)	Requisition against work done (In Lakh)	Remarks
Sl No	Package No				Length (Km)	Amount (In Lakh)	Initial Rectification with Surface Renewal	5 Year Routine Maintenance										
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
	MR-N/20-21 Samastipur/05	3201011033103	Chubgama Panchayat Bhawan to West Tola	3528 & 22.09.2020	1.00	46.908	31.040	11.565	27/08/2021-22.07.2021	02.07.2022	Complete	6.478	75	3.30	0	0	31.040	BT Completed
			Total			46.908	31.040	11.565							6.000	6.000	31.040	

- 1 Signed Hard Copy and Soft Copy (In Excel) of recorded IRI is enclosed.
- 2 Up-to-date Physical Progress has been uploaded in MES


 Executive Engineer
 RWD (W) Div, Samastipur
24.2.22

OFFICE OF THE EXECUTIVE ENGINEER RWD,
WORKS DIVISION, SAMASTIPUR

Name of Scheme :- Dhubgama Panchayat Bhawan to West Tola ,

Package No.- MR-N/20-21 Samastipur/05,

Project ID- 3201011033103

Certified that all item wise 100%
measurement has been taken by me



Junior Engineer

RWD Work Section, Pusa
Works Division, Samastipur

Certified that all item wise 50%
measurement has been checked by me



Assistant Engineer

RWD Work Sub Division, Pusa
Works Division, Samastipur

Certified that all item wise 10%
measurement has been checked by me



Executive Engineer
RWD Work Division
Samastipur

File :C:\Users\BRRDA118\Desktop\110244.xlsx Section No. :1, Eqn :test

Name of Customer :Abhey Kumar Thakur, Name of Work/ Road :Dhobgama Sima Panchayat Bhawan se Paschim.



1892

0.1

0.2

0.3

0.4

0.5

0.6

0.7

0.8

0.9

Distance * 1000 m

[Signature]
13/04/22
A.E. Puri

[Signature]
13/04/22
A.E. Puri

[Signature]
14/02/22
Executive Engineer
Executive Works Division
R. W. D. Works Division
Sumastipur

Date	Time	Section	Length	Bumps	Speed	OR	CATEGORY	IRI	Latitude	ongitude	Event			
13/2/22	10:31:2	1	0.1	380	0	3800	3790 G	4.96	25.96405	85.63916	Culvert	$Y = 0 * X^2 + 0.898 * X + 377.8$		
13/2/22	10:32:47	1	0.1	300	20.2	3000	3071 G	15.74	25.9647	85.63443	Normal	$X = 5600$		
13/2/22	10:33:0	1	0.1	280	20.2	2800	2892 G	3.89	25.96454	85.63347	Normal	$Y = 5406$		
13/2/22	10:33:0	1	0.1	300	20.2	3000	3071 G	4.11	25.96428	85.63253	Culvert			
13/2/22	10:33:23	1	0.1	300	20.2	3000	3071 G	4.11	25.96341	85.63242	Curve			
13/2/22	10:34:36	1	0.1	250	10.1	3012	3082 G	4.12	25.96261	85.63217	Normal	(R) RURAL ROAD		
13/2/22	10:34:51	1	0.1	300	20.2	3000	3071 G	15.74	25.9675	85.63423	Normal			
13/2/22	10:35:0	1	0.1	280	20.2	2800	2892 G	3.89	25.96444	85.63445	Normal			
13/2/22	10:35:0	1	0.1	300	20.2	3000	3071 G	4.11	25.94428	85.6321	Culvert			
13/2/22	10:35:23	1	0.1	300	20.2	3000	3071 G	4.11	25.96348	85.63241	Curve			

19/10/22
19/10/22

13/10/22
AREPUN

14/12/22
Executive Engineer
R. W. D. Works Division
Sumasipur