

~~पर्य का नाम :- ३०५४ :- GIRAN BADAJJI SE
RANCHAPUR VIA. DONE CANAI.~~

~~F.R. Kuchwaha 3054 u/02
New Raisthawar
30/5/21~~

~~Agency - Sutij~~

Measurement Book

Schedule XLV-Form No. 134

कार्यपालक अभियंता

ग्रामीण कार्य विभाग

कार्य प्रमंडल नरकाटेयागंज

DIVISION

प्रांगण :- गोनाघ

SUB-DIVISION

M.B.N. 1317 | 2020-21

Name of Work -

Situation of work -

Agency by which work is executed -

Date of measurement -

Date of measurement
No. and date of agreement -

No. and date of agreement
(These four lines should be repeated at the commencement
of the measurements relating to each work).

Particulars	Details of actual measurement				Contents of area	
	No.	L.	B.	D.		
<u>Ist RIA Bill</u>						
<u>Name of work —</u>						
Repair & seal farm						
Gram Bedauli to Kanchampur						
via Done Canal tank.						
Head - MR-3054						
Block - Grauntha.						
Agency - Suraj Kumar Kawshwaha.						

Agree. No — 89/302)

Dated of W.O. to C - 2020/20

Time required = 12 min

$$\text{Upper Value} = 30 \text{ minutes} + 12 \text{ minutes}$$

Length = 41.939 km

④ ~~Geographie~~ ~~Geographie~~ ~~Geographie~~

Amount of payment Apr. 9, 41205-00

5% of S.D	—	47,060 = 00
1% of I-T	—	9412 = 00
1% of CGST	—	9412 = 00
1% of SGST	—	9412 = 00
1% of Octroy	—	9412 = 00
Royalty	—	85950 = 00
S. Fee	—	41008 = 00
Total deduction	—	911666 = 00
By Cheque	—	729539 = 00
Total	—	941205 = 00

Passed do. by 9,412.05/- (Rupees -
Nine thousand four hundred and
two rupees) only

~~⑥ 211971~~

ग्रामीण सर्व विभाग, कार्य प्रमण्डल
Continuation of

~~Continuation~~ 28-10-29

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>Total Consumed material</u>					
① E/W	—	2600.00 m ³			
② C. Sand	—	2.00 m ³			
③ L-Sand	—	230.00 m ³			
④ Stone gravel	—	779.24 m ³			
⑤ Stone chipp	—	1082.00 m ³			
⑥ Stone screening	—	183.60 m ³			
⑦ Bitumin Emulsion(S-1)	—	4.74 m ³			
⑧ Bitumen Emulsion(RS)	—	5.85 m ³			
⑨ Bitumen (S-90)	—	60.54 m ³			
⑩ West Plastic	—	395 kg.			
Total 20-6-21					

- ① Work has been completed satisfactorily.
- ② Subsequent test has been done during execution of work.
- ③ No any other payment are due to contractor.

~~Total~~ 20-6-21

OB