

Inspection Report for Flood Damage work

Date:-

- 1 Name of PIUS :- Madhapura
2 Name of Block :- Murhans
3 Name of Road :- Raghunathpur Ward no-8 MC Bhami das Ice Chhar-se
Murho Jala Jale

A. For Road

- 1 Damage Location/Chainage :- 0+210m, 210+417m, 417+622, 622+1312m, 1312+1749m, 1749+1950
2 Damage Length :- 0.910 km
3 Nature of damage :-
4 Details of Restoration Works :-
i Material being used in Restoration works:- Bricks bats, H.P, cement bags
ii Equipments/Tools being used in Restoration works :-
iii Procedure taken up in Restoration works :-
iv Restored Length :-

B. For Bridge

- 1 Damage Location/Chainage :-
2 Damage Length :-
3 Nature of damage :-
4 Details of Restoration Works :-
i Material being used in Restoration works:-
ii Equipments/Tools being used in Restoration works :-
iii Procedure taken up in Restoration works :-
iv Restored Length :-

A. K. Nay
JE

Pringh
AE

EE

Signature
(Name of inspector)

Schedule XLV-Form No. 134

Modhepara

DIVISION

Murhiganj

SUB-DIVISION

Rajmakhpur waddho-8 Me Bhagani das ke char se

Measurement Book

Murho
mala jalk

Name to work—

Situation of work—

Agency by which work is executed—

Date of measurement—

No. and date of agreement—

(These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work—					
of Road from Begunahpur					
wardha & Mr. Khendidaske					
Chak. Ce. Murho Jala Jale.					
Agency—					
Panwariy Gadha					
Island final A/c bill					
providing and laying					
of R.M. bed					

6020 x 0.25	1 x 30 x 2.74 x 0.25 = 20.55
	2 x 30 x 2.74 x 0.30 = 49.32
	1 x 30 x 2.74 x 0.25 = 20.55
	1 x 30 x 2.74 x 0.15 = 12.33
	1 x 11 x 2.35 x 0.15 = 3.82
310 x 417	1 x 30 x 3.03 x 0.30 = 27.27
	2 x 30 x 2.74 x 0.25 = 41.10
	2 x 30 x 2.74 x 0.30 = 49.32
	1 x 30 x 3.03 x 0.15 = 13.63
417 x 622	2 x 30 x 3.03 x 0.30 = 54.54
	1 x 30 x 2.74 x 0.25 = 20.55
	1 x 10 x 2.43 x 0.15 = 3.64
	2 x 30 x 3.03 x 0.30 = 54.54
622 x 1312	3 x 30 x 3.03 x 0.40 = 109.08
	1 x 8 x 2.74 x 0.45 = 9.86
	2 x 30 x 3.10 x 0.45 = 83.70

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L	B	D	
	1X	22	3.03	0.45	29.99
	1X	23.78	3.35	0.45	31.86
1312 & 1343	1X	14.32	12.13	0.50	87.28
	1X	21.95	2.74	0.30	18.04
	3X	30	3.03	1.20	327.24
	1X	9	2.74	0.40	9.86
	1X	30	3.23	0.45	43.60
1743 & 1950	1X	21	3.65	0.50	38.32
	1X	30	3.65	0.50	54.75
					1214.19
Item-2	sand Filling in trench trenches do do all complete sh.				

	1X	30	4.22	0.60	72.00
	1X	21	3.65	0.60	45.99
					117.99
10% for H.P.	4	22	0.6	2x2.5	
					11.30
					106.68m

Item-3	Labour for filling empty cement bags with local sand.				
	2X	6x0.45	1.5		8.10
					238 bags.

Item-4	P/V and laying R.C.C pipe H.P.				
	2.5	4	100		

Continuation

