FIELD INSPECTION REPORT

| Date of I | aspection : / | 2/4/22 | District: Pulner_ | | |
|---|--|-------------------------|--|---------|----------|
| Division : | | 7-7- | Length (km): /.516 | 11 | |
| _ | the Road: 2 | 062 falizans | charge to There Ken | sha ho | |
| | Programme: | MAINTENANCE | | | |
| Package | | | Road Id No.: | | • |
| Ongoing/Completed/Under Mailleliance | | | | , | |
| Status of the Project: Ongoing Corp. Work is a case of: New Connectivity/Up gradation/ Maintenance | | | | | |
| 101.101. | | | THE PROPERTY OF THE PARTY OF TH | | |
| | | | | | T |
| a) | Road Junction | condition | | S/U | ł |
| | Condition of S | 8/0 | 1 | | |
| ь) | Riding Quality | \S/U | | | |
| c) | | 4S/U |] | | |
| d) | Road Camber Whether free from defects such as visible cracks, exposed | | | | 1 |
| e) | whether free | case of CC Pavement. | 11 as violete state, | Yes/No | 12A. |
| f) | Contraction Jo | Yes/No | ₹ | | |
| g) | Compaction o | Yes/No . | | | |
| 6) | | | | | |
| | C disign of | S/SIKI/U | | | |
| a) | Condition of head walls in Hume pipe culverts including its painting Condition of Abutment & Wing walls, Slab in RCC culverts | | | S/SRI/U | 7 |
| b) | Condition of Abutment & Wing Walls, Slab in Recommendation of railings/slab/approach for Bridges | | | S/SRI/U | 7 |
| c) | PARTY AND STREET | rattings/stat/approacti | | | |
| | Rost First | lire | | | 7 |
| a) | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | | | | |
| | reomplifice. | History - Case | | | 3 |
| a) | Status of ATI | R's & any others | | | ل |
| | | | | | * |

Overall Rating

| Satisfactory (S) | · |
|---|-----|
| Satisfactory but requires Improvement (SRI) | SKY |
| Unsatisfactory (U) | |

NAME: Chemban Camal Blaigar DESIGNATION: A.F., RND, Pulner

Scanned with CamScanner