

FIELD INSPECTION REPORT

Date of Inspection :	12/01/22	District:	Palmer
Division :	Palmer	Length (km):	2.515
Name of the Road:	Haldia RFO Road to Sankarali		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
General			
a)	Road Junction condition		✓SU
b)	Condition of Surfacing		SU✓
c)	Riding Quality		✓SU
d)	Road Camber		✓SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)		✓Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No✓
Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		✓S/SRI/U
c)	Condition of railings/slab/approach for Bridges		✓S/SRI/U
Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No✓
Compliance History			
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

NAME: Chandan K. Bhalga

DESIGNATION: A.E., RWD, Palmer

(Signature)
12/01/22