FIELD INSPECTION REPORT					
Date of Inspection :			District: Provide		
Division: Purmon			Length (km): 2.97 KM		
Name of the Road: Charri			kamaila.		
Scheme/Programme: MAINTENANCE					
Package No.:			Road Id No.:		
		Ongoing/Completed	eted/Under Maintenance		
Work is a case of:		New Connectiv ty/Up gradation/ Maintenance			
The mineral to be ellected to be ellected.					
	Payement 3.2	建筑 指数	THE STATE OF THE STATE OF		
a)	Road Junction condition			√S/U	
b)	Condition of Surfacing			S/U_	
c)	Riding Quality			\\$∕U	
ď)	Road Camber .			_S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of	Yes/No .			
Cross-Dialingo					
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			_S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3	Road Furniture				
a)	Whether sign b stones/Pavement	Yes/No			
	ComplianceHis	loty Tr			
a)	Status of ATR's	& any others			

Overall Rating

Satisfactory (S)	V
Satisfactory but requires Improvement (SRI)	>
Unsatisfactory (U)	U

NAME: Gaserdon Brasad Himery

DESIGNATION: J-E