## FIELD INSPECTION REPORT

Date of Inspection :			District: Purnea		
Division: Pyrneg			Length (km): 2.035 k-m		
Name of the Road: Matiya Granti to Khokhaban.					
Scheme/Programme: MAINTENANCE					
Package No.:			Road Id No.1		
Status of the Project: (		Ongoing/Completed/Under Maintenance			
Work is a case of: New Connectiv ty/Up gradation/ Maintenance			p gradation/ Maintenance		
图 图 图	行型制度的	Parametey & Ig.	ne cheeped	the second	
	taxement.		<b>可以外的中国的</b>	<b>建筑</b>	
a)	Road Junction	SAU			
b)	Condition of Surfacing			sau	
c)	Riding Quality			,SAU	
d)	Road Camber			.SAU	
e)	Whether free aggregates in c	Yes/No			
f)	Contraction Jo	YesANo			
g)	Compaction of	Yes/No .			
2,44	Growt Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			,\$/\$RI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.7	Road Furaltui				
a)	Whether sign stones/Pavemen	Yes/No			
	The second secon	BURNIA PROPERTY OF THE PROPERTY OF THE PARTY	THE RESERVE OF THE PARTY OF THE	THE RESIDENCE OF THE PARTY OF T	

Overall Rating

Satisfactory (S)	×
Satisfactory but requires Improvement (SRI)	7
Unsatisfactory (U)	V

NAME: Governotog fragad Himmey.

Status of ATR's & any others

DESIGNATION:

J. E

