# Inspection Report for Flood Damage Work

#### Date.:

- Name of PIUs RWD, works Division, Grobal agang- 2 1.
- Name of Block/Road Sidhwalla / Kateya tola to Kashi Terprodis 2.

#### A. For Road

- Damage Location/Chainage: 1. 3510 Mto 3590 M
- 2. Damage Length m 0.00
- 3. Nature of Damage : Road washout & worls or overtoppad
- Details of Restoration Works: 4.
  - i. Material being used in Restoration Work: Brick bots
  - ii. Equipment/Tools being used in Restoration Works: 3CB Tractor with Trolly
  - Procedure taken up in Restoration Works: iii.
  - iv. Restored Length : 10.0 m

### B. For Bridge

- Damage Location/Chainage : 1.
- 2. Damage Length
- 3. Nature of Damage
- 4. Details of Restoration Works:
  - i. Material being used in Restoration Works:
  - ii. Equipment/Tools being used in Restoration Works:
  - iii. Procedure taken up in Restoration Works:
  - iv. Restored Length

ग्रामीण कार्य विभाग

क्षार्थ प्रमण्डल हथुआ (गोपालगन)

Superintending Engineer

## Report.

Name of work

:- Kateya Tola to Kashi Tangrahi

Estimated Cost :- Rs 249350. 400

Total length of road :- 7.03 KM

Description :- The present estimate has been framed under the supervision of Assistant engineer in accordance with the order of Executive Engineer , RWD , WD Gopalganj-2 Vide Engineer – in – Chief , RWD ,Patna letter no – 4275 dated— 22-10-2021 . The part of above mentioned road has been damaged due to heavy rain/flood. And due to this damage the transportation has been obstructed . The immediate motorable work is necessary in public interest . Villagers will be benefitted by the completion of this motorable work.

In the estimate there has been a provision of repairing the damaged part of the road & making it motorable by filling brickbats. This provision has a purpose to put a check on the erosion of embankment along the road .

In this estimate the rate of raw materials and labour wages has been prepared after the analysis of new rate. This estimate is as per the specifications. The estimate is devoted to technical and administrative acceptance.

July 11-21

ble Work in road from Kateya tola to Kashi Tengarahi Amount

- Materoble Work in road its.	
Detailed Estimate For Motorable Work in road no.	1-2024
Detailed Estimate / Flood for Year . 202	
Detailed Estimate For Motorable Work III Toda Work III Tod	

L	damaged due to Heavy rain / Flood for Year . 202 . D (M.) Qty. unit							rate	Amount
S	. Items	no.	L (M.)	W M.)	D (M.)				-
	Providing brick bats billed in ditches including all cost of Labour & Material with	,					$M^3$		
	all complete job .  CH- 3510 M Emb	1	8.00	3.5 + 7.00/2	2.00	84.00 40.00	$\frac{M^3}{M^3}$		
	Ditch	1	8.00	5.00	1.00	124.00		. ,	218486.76
									26218.41
-	Add Gst @ 12%								2184.87
	Add Cess @ 1%								246890.04
									2468.90
15.8	Add 1% contigency	$\perp$						Total	249358.94
		_							249350.00
# t								con f	2, 2.49 len

Suy Rs 2.49 len.

Technically Squefroncol for Ry 2-49 lave (Ruples Two leve of forty Nine thousand) only

Superintending Engineer RWD Works Circle, Siwar