



Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
2nd and Final Bill					
Name of work: Repair of Road					
From Lakhaur to					
Devi Tal. Under					
New Maintenance					
Policy 2018 under					
M.R. 3054. Under					
Lakhaur Bishu					
Name of contractor: Shree					
Sanjay Kumar					
Suman					
Agreement No. 44 SBD/2019 -					
2020					
Date of work start: 12/12/2019					
Date of work end: 11/9/2020					
Below — 03.99%					
Date of Measurement: 27/3/21					
Measurement					
1. construction of sub-grade					
and earthen shoulder					
on comp sub grade					
$2 \times 12.0 \times 0.300 \times 0.300 = 2.16 \text{ M}^3$					
$2 \times 10.0 \times 30.0 \times 0.600 \times 0.300 = 108.0 \text{ M}^3$					
$2 \times 14.0 \times 30.0 \times 1.000 \times 0.300 = 302.0 \text{ M}^3$					
$2 \times 22 \times 30.0 \times 1.000 \times 0.300 = 396.0 \text{ M}^3$					
Continuation					
Total 808.16 M ³					

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Long Brickwork		B F	B L	1138	152 w
Paymen					
				(-) B 356	17592 w
TOTAL			B 5520		562 w
Done 24/12/2021 RE. Lalchand complete.					
 24/12/21 C.S.P.  24/12/21					

Material Statement As Per

2nd and Final Bill

(i) Earth work 2nd bill — 1323.56 m³
@ B 23 = 78 Per m³

(ii) Bricks — 5760 m³
@ B 5 = 24 Per m³

(iii) Coarse sand — 3.62 m³
@ B 150 = 80 Per m³

Done 24/12/2021
RE. Lalchand