

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of Road: - Temporary					
Restoration of Road					
From Begda passy path					
To Kamalpur					
Agency: -					
Head: F.D.R					
Actual length of Road - 1.831 km					
Flood affected Road length - 0.136 km					

Record entry					
(1)	Sand filling in				
	foundations Trenches				
	as per drawing				
	2 X	25	X	1.50 X	$\frac{0.90}{1.10} = 82.500m^3$
	1 X	15	X	2.25 X	$\frac{0.90}{1.25} = 42.188m^3$
	1 X	16.00	X	3.50 X	$\frac{0.95}{0.90} = 31.500m^3$
	2 X	25	X	1.40 X	$\frac{0.95}{1.50} = 105.00$
					<u>185.00</u>
					261.188

Continuation

14) Supply of
Bamboo at Site - 109.

~~48~~
~~22/11/2021~~
~~86~~

~~48~~
~~22/11/2021~~
~~012~~

Scanned with CamScanner

ABSTRACT COST

9

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L	B.	D.	
(1)	Sand Filling in				
	foundations d/c				
	Qty vide Tmp (p) 6				
	264.155 m ³ @ 582.71/m ³				
				RS = 152176 = 85	
(2)	Labour for cutting				
	62mm to 75mm dia				
	bamboo piles d/c				
	Qty vide Tmp (p) 7				
	422.50 m @ 45.84/m				
				RS = 19421 = 71	
(3)	Labour for				
	8 Ply 75mm dia				
	bamboo sponner				
	d/c				
	Qty vide Tmp (p) 7				
	231.00 m @ 5.31/m				
				RS = 1226.61	
(4)	Supplying &				
	putting of bamboo				
	at site d/c				
	Qty vide Tmp (p) 7				
	107.00 m @ 188.37/m				
				RS = 20534 = 51	

Continuation

RS = 1,93,379 = 68

R. S. R. = 193 377-68

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(15)	Labour filling				
	empty cement				
	bags with local				
	Sand do do				
	Q. of vide 11.656				
	11.656.000 @ 37.05/100				
				RS = 431854-80	
				total RS = 6,25,234 = 48	
	add 12% G.S.T @ RS = 75028 = 13				
	add 1% Labour cess @ RS = 6252 = 34				
	seigniorage fees @ 10% bank			9326.63	
				total RS = 7,15,841 = 58	

Say RS = 7,15,842 = 00

23-11-2021
 23-11-2021
 23-11-2021

23-11-2021
 23-11-2021
 23-11-2021

Continuation