

KHARUA MAIN ROAD TO MONIYA TOL (F.P.R.)

Schedule XLV-Form No. 134

Thantharpu

DIVISION

Thantharpu

SUB-DIVISION

3073

MEASUREMENT BOOK

Name to work — 1
 Situation of work —
 Agency by which work is executed —
 Date of measurement —
 No. and date of agreement —
 (These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L	B	D	
CH - F.D.R.					
Name of work: -	Mortable of floor damaged				
	dood from Karan				
	main dood to Nombu				
	tol under F.D.R.				
Agency: -	Departmental				
Date of entry: -	10.5.22				
	work done				
	Measurement as per TS				
(1) providing and filling					
bride batts in ditched and					
damaged embankment					
including cost of bride					
batts and labour charge					
as per E/S					
CH - 300M	1x	16.60x	$\frac{1.2+1.40}{2}$	0.60	11.95M ³
" "	1x	22.20x	$\frac{0.9+1.20}{2}$	0.45	10.63 "
" "	1x	17.60x	$\frac{0.8+1.20}{2}$	0.30	5.544 "
" "	1x	10.00x	$\frac{0.2+1.20}{2}$	0.45	4.725 "
" "	1x	13.10x	$\frac{0.9+1.20}{2}$	0.45	6.189 "
" - 460	1x	11.60x	$\frac{0.9+1.40}{2}$	0.30	4.176 "
" "	1x	8.00x	$\frac{1.0+1.30}{2}$	0.30	3.120 "
" 600M	1x	6.00x	$\frac{0.8+2.0}{2}$	0.30	3.648 "
" 680	1x	5.80x	0.90x	0.30	1.56 "

Continuation

410.51542143

C4-1060	1x 5.20 x	$\frac{1.80+1.50}{2}$	x 0.45	3.34 "
" "	1x 6.90 x	$\frac{1.90+1.20}{3}$	x 0.45	4.96 "
" 1080	1x 5.40 x	$\frac{1.20+1.0}{2}$	x 0.25	0.93 "
" 1090	1x 8.50 x	$\frac{1.30+1.20}{2}$	0.30	3.18 "
C4-1740-1745	1x 5.00 x	1.00 x	0.60	3.00 "
				105.098 M ³
	10.5.22			
	7.6'			
	16.05.00			

Inspection Report of Flood Damage Work

Name of PIUs :- RWD Works Division, Jhanjharpur

Name of Block :- Jhanjharpur

Name of Road :- Kharauq main road to Noniya tol

A. For Road

1. Damage Location Chainage :- 300 to 1745
2. Damage Length :- 240.9
3. Nature of Damage :-
4. Details of Restoration Works
 - i. Materials being used in restoration works:- Bricks Bad's
 - ii. Equipment's/Tools being used in Restoration works:- tractor
 - iii. Procedure taken up in Restoration works:- 105.098m
 - iv. Restored Length:-


B. For Bridge

1. Damage Location Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works
 - i. Materials being used in restoration works:-
 - ii. Equipment's/Tools being used in Restoration works:-
 - iii. Procedure taken up in Restoration works:-
 - iv. Restored Length:-


C. Requirement Of New CD/ Bridges

- i. Name of Road:-
- ii. Location/ Chainage:-
- iii. Type of CD Work/ Length required:-

"S"


23/4/22
JE
Signature of JE/AE/EE


RR
23/4/22


23/4/22
Signature
(Name of Inspection)

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
ABSTRACT OF COST.					
(1) Providing and filling bridge batts in ditches and drainage and embankment including cost of bridge batts and labour charge as per E/t					
Qty vide T.M.B.P. - 1(1)					
105.098 m ³ @ 2004-96/m ³					210717=00
Add 12% GST.					25286=00
Add 1% L.C.					2107=00
Add 10% S.F.					10846=00 11172=00
(105.098 X 1082) X 10%					249282=00

Rs 248956=00

10.5.22

J.E.

10.5.22
J.E.