

Schedule XLV-Form No. 134

Motorsable of Road from PMGSY Path Groom
Toka Bigha Tak Path Nirman.

948

DIVISION

948

SUB-DIVISION

MEASUREMENT BOOK

948

प्रमाणित किया जाता है कि इस मापी हुई
 में मसाले में दिये हुए 100 (एक सौ) रुपये
 हैं जो सहपात्र श्रीमानों को एक एक
 और एक प्रमाणित पंजी के नाम
 प्रमाणित किया जाता है


 05.04.2014

कायपालके आभयन्ता
 प्राचीन कार्य विभाग
 कार्य प्रमंडल, हरनौत
 सि.प.म.

Sch. XLV—Form No. 134

Harinout DIVISION
 _____ SUB-DIVISION

Measurement Book

No. 948

Name of Officer _____

Date of first entry _____

Date of last entry _____

rk—

1

1

1

1

1

1

1

2

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Construction of granular sub-base do do = 75					
7.50m ³ (V.T. m. B.P. No - 01)					
② 18.3230.18/m ³ 18.24226 = 00					
					18.24226 = 00
C. 18.3230.18/m³ 18.24226 = 00					
5-9-21					
A.E					
					05/09/21
					J.E

INSPECTION REPORT FOR FLOOD DAMAGE WORK

Date :

1. Name of PIUS :- RWD Works Division Haranaut.
2. Name of Block/Road :- Chandli / Motorable of road from PMSY Path to Gram Te Ka Bigha.

A. For Road :

1. Damage Location/Change :- 330m
2. Damage Length :- 3.00m
3. Nature of Damage :- Due to excess Rainfall.
4. Details of Restoration Works :-
 - i. Material Being used in Restoration works :- G3B material
 - ii. Equipment's / Tools being used in Restoration works :- Tractor, Trulli, JCB, etc
 - iii. Procedure taken up in restoration works :- G3B material used in road carriage
 - iv. Restored Length :- 3.00m

Dr. 25/11/21

B. For Bridge :

1. Damage Location / Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - i. Material Being used in Restoration works :-
 - ii. Equipment's / Tools being used in Restoration works :-
 - iii. Procedure taken up in restoration works :-
 - iv. Restored Length :-

C. Requirement of New CD/Bridge :

- i. Name of Road :-
- ii. Location Chainage :-
- iii. Type of CD work/Length required :-

- Upload one photograph of damaged portion if available
-
- Attach minimum two photograph (during restoration & after restoration) photographs should be Geotags and at least one photo be captured in selfie mode. Work is satisfactory.

Signature of

JE

AE

EE

Dr. 25/11/21

B. E.

E. W. D. Raju