(FDR)

Schedule XLV-Form No. 134

NH30A To poari Kharathua Road

DIVISION

SUB-DIVISION

MEASUREMENT BOOK

942

Scanned by TapScanner

प्रमाणित किया जाता है कि इस मापपुस्तिका में मशीन से छपे कुल 100 (एक सौ) पृष्ठ हैं जो लेखाकर्म अभिलेखों 910 व 911 वर्ष अन्तर्गत कार्यमंडल हरनौत के नाम निर्गत किया जाता है

03.04.2021

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, हरनौत
3.4.21

Sch. XLV—Form No. 134

Harnaut DIVISION

SUB-DIVISION

Measurement Book

No. 942

Name of Officer

Date of first entry

Scanned by TapScanner

Pre Measurement

Name fo work— 1
Situation of work—
Agency by which work is executed—
Date of measurement—
No. and date of agreement.
(These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of Road:- HH 30A to					
Pobore Kharathua Road					
Date of Entry:- 25/8/21					
G.S.B.					
$3.00 \times 3.50 \times \frac{0.80 + 1.00 + 0.8}{3}$				=	$9.10 M^3$

ABSTRACT OF COST

(1) Name of work :- NH 30A to Poari Kharathua Road

(2) Agency :- Sri Prem Sinha

(3) Date of entry - 25.8.2021

Payment made following items

Items

(1) Supply GSB with carriage at site including labour

——— do ——— Qr

TMB page (1) = 9.10 M^3

@ Rs 3230=18/M^3 — Rs 29,394=

Continuation Rs 29394=00

C&P
25.08.2021

NSK
25.8.21
AE

25.8.21
J.E.

Scanned by TapScanner

INSPECTION REPORT FOR FLOOD DAMAGE WORK

Date :

1. Name of PIUS :- R.W.D Works Division Harnaut
2. Name of Block/Road :- Harnaut – NH30A To poari Kharathua

A. For Road :

1. Damage Location/Change :- 100m.ch.
2. Damage Length :- 3.0m
3. Nature of Damage :- Roadway Damage
4. Details of Restoration Works :- G.S.B filling
   i. Material Being used in Restoration works :- G.S.B
   ii. Equipment's / Tools being used in Restoration works :- Tractor, Roller, etc.
   iii. Procedure taken up in restoration works :- G.S.B material used in Roadway.
   iv. Restored Length :-

B. For Bridge :

1. Damage Location / Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
   i. Material Being used in Restoration works :-
   ii. Equipment's / Tools being used in Restoration works :-
   iii. Procedure taken up in restoration works :-
   iv. Restored Length :-

C. Requirement of New CD/Bridge :

i. Name of Road :-
ii. Location Chainage :-
iii. Type of CD work/Length required :-

- Upload one photograph of damaged portion if available
-
- Attach minimum two photograph (during restoration & after restoration) photographs should Geotags and at least one photo be captured in selfie mode. Work is satisfactory.

Signature of JE 22/11/21 AE 22-11-21 EE 22-11-21 22/11/21

Executive Engineer
Works Department
Division, Raj

Scanned by TapScanner