

(F.D.R)

Schedule XLV-Form No. 134

Name of Road - R.W.D Road under Budha-
Khad panchayat from Hornant block Road
to paras diha p.w.D Road via Balwa
Kharjama.

95
2/11/21
DIVISION

11/11/21
SUB-DIVISION

MEASUREMENT BOOK

952

प्रमाणित किया जाता है कि इस भागी
पुस्त में दर्ज है धर्म पुस्त 100/100
को पुस्त है जो लहापद अभिलेख
शत 0 100 कार्य कर प्रमाणित
नगरीसा के नाम निर्धारित किया जाता
है

05.04.2021

कार्यपालक अभियन्ता
ग्रामीण कार्य विभाग

कार्य प्रभार, हरनौत
5.4.21

Sch. XLV—Form No. 134

tiernaw DIVISION
NAGAR NAUSA SUB-DIVISION

Measurement Book

No. 952

Name of Officer _____

Date of first entry _____

Date of last entry _____

Name of work—

Situation of work—

Agency by which work is executed—

Date of measurement—

No. and date of agreement.

(These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
pre-measurement.					
Name of work: -					RWD Road
under budha Khad panchaya					
from Harnaut block Road					
to paras diha PWD Road					
via Balwa Kharjama.					
Date of entry -					15/11/2021
					<u>items.</u>
(1) Local sand b					

$$\frac{8.00 \times 2.50 + 1.10 \times 3.66}{2} = 52.70 \text{ M}^3$$

$$\frac{52.70 \times 35.38}{1.20} = 1552 \text{ bags.}$$

Cent empty bags = 1552 bags.

(2) Supply of sand with carriage
 (3) Supply of 14 Nos = 52.78 M³

TO 6 NOS

~~10/11/2021~~
 E.E.

10/11/2021
 A.E.

10/11/2021

J.E.

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>ABSTRACT OF COST</u>					
(1) Supplying empty cement bags — do					
TMB page (1) = 1552 NOS					
@ ₹ 8 = 2/NOS — ₹ 13,533 =					
(2) Supplying sand with Carriage — do					
TMB page (1) = 52.78 m ³					
@ ₹ 340 = 94/m ³ — ₹ 17,998					
(3) Supplying unskilled labour — do — G.P.					

TMB page (1) = 106 NOS				
@ ₹ 329 = 96/each ₹ 34,837 =				
				₹ 66,368.20
<div style="display: flex; justify-content: space-between;"> <div> <p><i>C.P.P.</i></p> <p><i>for</i></p> <p><i>10.11.2021</i></p> <p><i>10/11/2021</i></p> <p><i>A.B.</i></p> </div> <div> <p><i>10/11/21</i></p> <p><i>J.E.</i></p> </div> </div>				

INSPECTION REPORT FOR FLOOD DAMAGE WORK

Date :

1. Name of PIUS :- R.W.D. works Division Harnaut
2. Name of Block/Road :- Nagamausa - RWD Road under Budhakh Panchayat from Harnaut block Road to PWD Road via Balwa Kharjama.

A. For Road :

1. Damage Location/Change :- AT CH-4320M.
2. Damage Length :- 6.50M.
3. Nature of Damage :- Plank Damage
4. Details of Restoration Works :- Sand bags filling, with bamboo piling
 - i. Material Being used in Restoration works :- Sand, empty cement bags & b.
 - ii. Equipment's / Tools being used in Restoration works :- Tractors, bamboo, J.C.B.
 - iii. Procedure taken up in restoration works :- G.S.B G8-II material used
 - iv. Restored Length :- in Road in Carriage width.

B. For Bridge :

1. Damage Location / Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - i. Material Being used in Restoration works :-
 - ii. Equipment's / Tools being used in Restoration works :-
 - iii. Procedure taken up in restoration works :-
 - iv. Restored Length :-

C. Requirement of New CD/Bridge :

- i. Name of Road :-
- ii. Location Chainage :-
- iii. Type of CD work/Length required :-

- Upload one photograph of damaged portion if available

•

- Attach minimum two photograph (during restoration & after restoration) photographs should be Geotags and at least one photo be captured in selfie mode. *Work is satisfactory.*

Signature of

[Signature]
JE

[Signature]
AE

[Signature]
EE

[Signature]
Executive Engineer
Rural Works Department
Works Division, Rajgir