

(F.D.R)

Name of Road: - Hiralan Bishta to
Tampur Mushahari, M.B.M 934

Measurement Book

Schedule XLV-Form No. 134

Harnaul

DIVISION

Harnaul

SUB-DIVISION

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>ABSTRACT OF COST</u>					
(1) Name of work:-					Hirdan bigh
					to Ilampur Mughari
(2) Agency:-					Sai prem Sinha.
(3) Date of Entry:-					02.10.2021
<u>Payment made following items</u>					
					9 items
(1) Supply of cement					1707
					bags at site - do
					TRB Page (1) = 3420 NOS
					of 8.72/each - Rs 29822

(2) Supplying sand with
carriage — do — 120

TMB page (1) = 116,32 M³

eR 340 = 94 / M³ — ₹ 39,660

(3) Supplying Bamboo
with carriage — do

TMB page (1) = 13 NOS

eR 16 = 95 / NOS — ₹ 220 =

(4) Supplying unskilled
labour — do — 195

TMB page (1) = 233 NOS

eR 329 = 96 / NOS (₹ 76,881) =

₹ 1,46,583 =

limit ₹ 1,46,500 = 00

C & P
02.10.2021
Continuation
N.S.H.
2.10.21
AB

J.E.
2.10.21

INSPECTION REPORT FOR FLOOD DAMAGE WORK

Date :

1. Name of PIUS :- R.W.D works Division Harnaut
2. Name of Block/Road :- Harnaut :- Hirdan bigha to Idampur Mushe

A. For Road :

1. Damage Location/Change :- CH-100M
2. Damage Length :- 14M ✓
3. Nature of Damage :- Flank Damage
4. Details of Restoration Works :- Bamboo, sand bags filling bamboo.
 - i. Material Being used in Restoration works :- Bamboo, sand bags, empty car
 - ii. Equipment's / Tools being used in Restoration works :- Tractor, J.C.B,
 - iii. Procedure taken up in restoration works :- Sand bag used in Road
 - iv. Restored Length :- embankment.

B. For Bridge :

1. Damage Location / Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - i. Material Being used in Restoration works :-
 - ii. Equipment's / Tools being used in Restoration works :-
 - iii. Procedure taken up in restoration works :-
 - iv. Restored Length :-


C. Requirement of New CD/Bridge :


- i. Name of Road :-
- ii. Location Chainage :-
- iii. Type of CD work/Length required :-


- Upload one photograph of damaged portion if available


- Attach minimum two photograph (during restoration & after restoration) photographs should be Geotags and at least one photo be captured in selfie mode. Work is satisfactory.

Signature of


JE


AE


22-11-2021
EE


Executive Engineer
Rural Works Department
Works Division, Rajgi