

(E.D.R)

Name of Road:- Green Pachayat Bazar to Bazar
Parikosthaan Road

MBM 933

Measurement Book

Schedule XLV-Form No. 134

Harnaul

DIVISION

Harnaul

SUB-DIVISION

ਪ੍ਰਮਾਣਿਤ ਹਿਸਾਬ ਆਰਾਮ ਦੇ ਅਤੇ ਸਾਰੀ
ਫੀਟ ਮੇਂ ਫੁਲ ਫੀਟ 100 ਫੁਟ ਹੈ ਜੋ ਸਰਕਾਰ
ਅਧਿਕਾਰਿਤ. ਪ੍ਰਮਾਣਿਤ ਹਿਸਾਬ ਆਰਾਮ, ਸਾਰੀ ਸਮਾਂ
ਫੁਟ ਮੇਂ ਫੁਲ ਫੀਟ ਦੇ ਆਰਾਮ ਦੇ ਹਿਸਾਬ ਆਰਾਮ
ਆਰਾਮ ਹੈ।

[Signature]
6/3/21

ਫਾਇਨਲ ਆਰਡਰ
ਫਾਇਨਲ ਆਰਡਰ
3/3/21

Sch, XLV-Form No. 134

Harwaul DIVISION

Harwaul SUB-DIVISION

Measurement Book

No. 933

Name of Officer _____

Date of first entry _____

Date of last entry _____

Pre Measurement

1

Name of Work -

Situation of work -

Agency by which work is executed -

Date of measurement -

No. and date of agreement -

(These four lines should be repeated at the commencement of the measurements relating to each work).

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of Road:-	Gram panchayat				
	brah to prah parice wahan Road				
Date of Entry:-	09/10/2021				
Brick batty	9/10/21				
	$\frac{40.10 \times 25.10}{2}$		$\frac{2.10 + 1.10}{2}$	$\times \frac{2.2 + 1.80}{2}$	
					$= 97.50 \text{ m}^3$
	$9 \text{ m} \times 2.10 \times 1.50 \text{ m}$				$= 27.10 \text{ m}^3$

$$\frac{25.40 \times 2.80 + 2.40 \times 2.20 + 2.40}{2} = 12.60$$

$$\text{Net qty} = \frac{12}{14} \times 250.50 = 214.71 \text{ m}^3$$

~~19-10-21~~

NK/L
19-10-21
AB

09/10/21
J.E.

(2) Carriage — 214.71 m³

(3) unskilled labour for Bricks — 256 Nos

(4) Empty cement bags — 770 Nos

(5) Supplying sand with Carriage — 26.19 m³

(6) Supplying bamboo with Carriage — 50 STD

(7) Supplying unskilled labour for sand bags — 52 Nos

Continuation

12/10/21
J.E.

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>ABSTRACT of Cost</u>					
(1) Name of work:-	Grazon pan-				
Chayat	Brah to Brahpani				
Wahan	Recod				
(2) Agency:-	Sri prem K Sinha				
(3) Date of entry -	12.10.21				
Payment made following items					
<u>entry.</u>					
(1) Supplying Bricks					
bats at site - do - 670					
TMB Page (1) =	214.71 M ³				
of 1201 =	121 M ³ - Rs 257892				

(2) Carriage for Bricks
bat — do — 40

$$\text{TMB page (1)} = 214.71 \text{ M}^3$$

$$\text{Rs } 575 = 95 \text{ M}^3 \text{ — Rs } 1,23,662$$

(3) Supplying unskil-

led labour — do — 40

$$\text{TMB page (1)} = 256 \text{ Nos}$$

$$\text{Rs } 329 = 96 \text{ /each Rs } 84,470$$

(4) Supplying empty

cement bags — do

$$\text{TMB Page (1)} = 770 \text{ Nos}$$

$$\text{Rs } 8 = 72 \text{ /each — Rs } 6,714$$

$$\text{Rs } 472,738 = \text{w}$$

1

Rs 499,673 = 00

COP
12-10-21

Nash
12-10-21
AR

J. E.
12/10/21

INSPECTION REPORT FOR FLOOD DAMAGE WORK

Date :

1. Name of PIUS :- R.W.D Works Division Harnaut
2. Name of Block/Road :- Harnaut :- Gram panchayat Brah to Borah
panwahan Road.

A. For Road :

1. Damage Location/Change :- CH-750 M.
2. Damage Length :- 40 M.
3. Nature of Damage :- Blank Damage
4. Details of Restoration Works :- Brick bats filling, bamboo, sand bags
 - i. Material Being used in Restoration works :- Brick bat, bamboo, sand bags
 - ii. Equipment's / Tools being used in Restoration works :- Tractor, J.C.B, etc.
 - iii. Procedure taken up in restoration works :- Brick bats used in Road
Carriage in 1.50 m wide
 - iv. Restored Length :-

B. For Bridge :

1. Damage Location / Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - i. Material Being used in Restoration works :-
 - ii. Equipment's / Tools being used in Restoration works :-
 - iii. Procedure taken up in restoration works :-
 - iv. Restored Length :-


C. Requirement of New CD/Bridge :

- i. Name of Road :-
- ii. Location Chainage :-
- iii. Type of CD work/Length required :-

- Upload one photograph of damaged portion if available


- Attach minimum two photograph (during restoration & after restoration) photographs should be Geotags and at least one photo be captured in selfie mode.

Signature of


JE

NLS
22-11-21
AE

EE


22/11/21
Executive Engineer
Rural Works Department
Works Division, Rajgir