

(F.D.R)

Name of Road:- Pmushy Road Harmanaut to
Jalgaonbath (Daili) MBM 935
Village

Measurement Book

Schedule XLV-Form No. 134

३२०१/२

DIVISION

३२०१/२

SUB-DIVISION

ਪ੍ਰਮਾਣਿਤ ਹਿਸਾਬ ਵਾਲਾ ਹੈ ਅਤੇ ਇਸ
ਦੁਆਰਾ ਕੁਲ ਰਕਮ 100 ਲੱਖ ਹੈ ਜੋ
ਸਰਕਾਰੀ ਅਧਿਕਾਰਤ ਅਥਰਿਟੀ ਕਰਕੇ ਗਿਣਤੀ
ਜਾਂ ਪ੍ਰਮਾਣਿਤ ਹੋਣੀ ਦੇ ਕਾਰਨ ਹੋ
ਸਕਦਾ ਹੈ ਹਿਸਾਬ ਵਾਲਾ ਹੈ

30.03.2024

ਸਰਕਾਰੀ ਅਧਿਕਾਰਤ
ਅਥਰਿਟੀ ਕਰਕੇ ਗਿਣਤੀ
ਜਾਂ ਪ੍ਰਮਾਣਿਤ ਹੋਣੀ ਦੇ ਕਾਰਨ ਹੋ
ਸਕਦਾ ਹੈ

Sch, XLV-Form No. 134

Harmandir

DIVISION

Harmandir

SUB-DIVISION

Measurement Book

No. 935

Name of Officer _____

Date of first entry _____

Date of last entry _____

pre measurement

1

Name of Work -

Situation of work -

Agency by which work is executed -

Date of measurement -

No. and date of agreement -

(These four lines should be repeated at the commencement of the measurements relating to each work).

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	

Name of Road - PMHSY Road

Harraut to Jalgaon

path (Daili) village

Date of entry - 2/10/2021

① Bricks batts

$$17.00 \text{ m} \times \frac{2.50 + 1.00}{2} \times 2.00 = 59.50 \text{ m}^3$$

$$9.00 \text{ m} \times \frac{2.00 + 0.90}{2} \times 1.20 = 15.68 \text{ m}^3$$

$$75.16 \text{ m}^3$$

(2) Unskilled labour - 80 Nos

(3) Carriage or Bricks - 64.42 m³

3/10/21
NCP
3-10-21
AB
2/10/2021
J.E.

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>ABSTRACT OF COST</u>					
(1) Name or work:-	PM 434				
Harnant to Jal gobind path					
(Daili) in Nalanda District					
(2) Agency:-					
(3) Date of entry:-					
3/10/21					
(1) Supplying of Bricks					
bat at site - do - 4/8					
TMB Page (1) = 64.42 m ³					
at Rs 1201 = 121 m ³ - Rs 77,376					

(2) Carriage of Bricks					
bat - do - 4/8					
TMB Page (1) = 64.42 m ³					
at Rs 675 = 95 m ³ - Rs 37,217 =					
(3) Supplying unskilled					
labour for Bricks					
bat - do - 4/8					
TMB Page (1) = 80 NOS					
at Rs 329 = 961 NOS - Rs 22,602					
	Rs 1,37,195 =				

C.R. for
 02/10/21
 NGL
 2-10-21
 AB
 2/10/21
 J.E.

INSPECTION REPORT FOR FLOOD DAMAGE WORK

Date :

1. Name of PIUS :- R. W. D Works Division Harnaut.
2. Name of Block/Road :- Harnaut - PMHSY Harnaut to Jalgo bind path village

A. For Road :

1. Damage Location/Change :- CH. 1.80 Km
2. Damage Length :- 26m ✓
3. Nature of Damage :- Plank Damage
4. Details of Restoration Works :- Brick Bat Filling
 - i. Material Being used in Restoration works :- Brick bats
 - ii. Equipment's / Tools being used in Restoration works :- Tractor, J.C.B. Roller Etc
 - iii. Procedure taken up in restoration works :- G.S.B material used in Road to in Carriage width.
 - iv. Restored Length :-

B. For Bridge :

1. Damage Location / Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - i. Material Being used in Restoration works :-
 - ii. Equipment's / Tools being used in Restoration works :-
 - iii. Procedure taken up in restoration works :-
 - iv. Restored Length :-


C. Requirement of New CD/Bridge :


- i. Name of Road :-
- ii. Location Chainage :-
- iii. Type of CD work/Length required :-


- Upload one photograph of damaged portion if available


- Attach minimum two photograph (during restoration & after restoration) photographs should be Geotags and at least one photo be captured in selfie mode

Signature of


JE


AE


EE


22/11/24

Executive Engineer
Rural Work. Department
Works Division, Rajgir