

F.D.R.
R.E.O. Road to Pandeytola
(VR 11)

Measurement Book

No. : 64

Chakia

Kesaria

पुनर्निर्माण किया जाता है।
 26 मार्च 1981 में 'मन्त्री'
 द्वारा अंकित तुलना
 पृथ्वी (1981) तुलना है।
 1981 (1981) अंकित तुलना
 मार्च 1981 में 'मन्त्री'
 निर्माण किया जाता है।

1981

कार्यपालक अभियंता
 ग्रामीण कार्य विभाग
 कार्य प्रमण्डल, चकीया

Sch. XLV—Form No. 134

Chakia DIVISION
 Kesaria SUB-DIVISION

Measurement Book

No. 64

Name of Officer _____

Date of first entry _____

Date of last entry _____

Name to work—
 Situation of work—
 Agency by which work is executed—
 Date of measurement—
 No. and date of agreement.
 (These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
CH-Head-ABR 3054/24-22)					
Name of work. — Repair of Road.					
breach (Damaged by flood)					
for Motorability in L.O. 31 R.E. 0.70					
Pandey Tola. (VR 11)					
Agency — Departmental.					
Authority — E.E. R.A.D. (W)					
Division Chakia.					

<u>Record entry</u>					
① Providing and labour for					
laying brick bats (Prig)					
$2 \times 31.00 \times 3.00 (W) \times 2.00 = 372.00$					
					372.00M ³
Est. 412/22 2E					

Continuation

[illegible]

Scanned with CamScanner