

Emergency work :-

Sch. XLV—Form No. 134

13

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work :- Emergency Repair					
work, due to heavy flood/rain					
Damaged Road from Telki to					
Tital. Bigla Road,					
Agency :- Smt. Ashok Kumar					
Telanabad,					
Authority :- G.E.R.W.P., Telanabad,					
Date of Entry :- 08/09/21.					
Item No. Bricks, Bat Filling in.					
(1/1) Damaged Road from					
Telki to Tital Bigla Road					

— d — d —					
near, Bridge Ramp location					
①	1 x 4.70 x	(2.80 + 3.90 + 2.80)			17.20m ³
	x	(1.40 + 1.50 + 1.20)			
②	1 x 4.10 x	(2.90 + 3.50 + 4.90)			30.10m ³
	x	(2.50 + 1.90 + 1.80)			
					47.30m ³
					57.60m ³
					08/09/21

08/09/21

Continuation

A.C.

8.9.2021
F.E.

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of Work: → Emergency Repair work, due to heavy flood/drain Damaged Road from Jalki to Titai. Bigla Road.					
Agency: → SSI - Akhola-Kumar, Jehanabad.					
Authority: → G.E.R.W.D, Jehanabad.					
Date of Entry: → 08/09/21.					
Item No. BRICKS. Bat Filling in.					
(1/1) Damaged Road from Jalki to Titai Bigla Road					

— d — d —					
Near, Bridge Ramp location					
① $1 \times 4.40 \times (2.50 + 3.20 + 2.80) / 3$					17.20m ³
$\times (1.45 + 1.50 + 1.20) / 3$					—
② $1 \times 4.10 \times (2.90 + 3.50 + 4.20) / 3$					30.10m ³
$\times (2.50 + 1.90 + 1.80) / 3$					—
Total Qty =					47.30m ³ 57.60m ³ — 08/09/21

08/09/21
J.E.
Continuation
A.C.
8-9-2021
F.E.

