

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :-

2 Name of Block/Road :-

E.E Rihid Hajipur
Bhagwanpur / Bhagwanpur to Paksi

(A) For Road:

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-

~~Bhagwanpur to Bhagwanpur~~
In km 4th and 2nd.
0.175 K.M
Flood

- (i) Material being used in Restoration works:-
- (ii) Equipment's/Tools being used in Restoration works:-
- (iii) Procedure taken up in Restoration works:-
- (iv) Restored Length :-

Brick Buds Qty = 47.67 M³


(B) For Bridge:


NA


Work is satisfactory.

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-

- (i) Material being used in Restoration works:-
- (ii) Equipment's/Tools being used in Restoration works:-
- (iii) Procedure taken up in Restoration works:-
- (iv) Restored Length :-


28/10/21
JE
Signature of JE/AE/EE


28/10/21
AE


04/11/21
Signature

(Name of Inspection)

Restoration work of the road from Imadpur to Pakri under F.D.R of 2021-22.

- (1) Providing, laying, spreading and compacting Brick Bats including spreading in uniform thickness hand packing (Manual means) — do — job.

Qty vide MB No. 2812 P. No. 16 ~~98,418 = 50~~
~~108,200/-~~
~~2267.78~~
~~2161.18~~ / M³ ~~2064.56~~ ~~Rs 1,03,023/-~~

Total Rs ~~1,03,023/-~~
~~98,418 = 50~~
 Say Rs ~~1,03,050/-~~
~~108,200/-~~
~~98,500/-~~

May
 26/10/21

J.E

R.W.D
 (W) Section
 Bhagwanpur

26/10/21

A.E

R.W.D
 (W) Sub. Div
 Bhagwanpur

26/10/21

E.E

R.W.D
 (W) Division
 Hojipur

As Per S.E. RWD (M) Circle Muz.
 Letter No. 1179 Dated 01/10/2021
 Estimate has been verified by inspecting
 E. E. RWD. (M) Division Muz. West

Technically sanctioned for Rs. 0.985 lac
 (Rs. Ninty eight thousand five hundred) only
 (provisionally)

27/12/21
 Superintending Engineer
 Rural Works Department
 Work Circle, Muzaffarpur