

Inspection Report for Flood Damaged Work in the year 2021-22

Date of Inspection :- 20.12.21 Name of PIU :- RWD (W) Div. *Darbhanga-2*
Name of Block :- MADHWAPUR
Name of Road :- L038 TO BARI POKHAR
For Road :-

1. Damage Location/ Chainage :- CH. 0.00 KM

2. Damage Length :- 63m

3. Nature of Damage :- Pot holes

4. Details of Restoration Works :- 51.88 m³

i. Material being used in Restoration Works Brick Bats

ii. Equipment's/ Tools being used in Restoration Works Tractor & Roller

iii. Procedure taken up in Restoration Works Filling & Compaction

iv. Restored Length 63m

Remarks :- Work found Satisfactory

[Signature]
20.12.21
Signature of JE/AE

[Signature]
20/12/21
Signature of E.E

**Estimate for Restoration work of Road from L038 to Bari Pokhar Road for the year 2020-2021
in Madhawapur Block**

Length-2.375 KM

Sr NO.	Item of Work							
1	Labour for lying dry graded jhama khoa or Stone filter under Brick pitching in slope or apron including including light ramming etc. all complete as per approved design, specification and direction of E/I (Brick Bats).							
ch	Nos	Length	Width	Height	Quantity	Unit	Rate	Amounts
0.00	1	42.00	2.50	0.60	63.00	Sq. M	44	
	1	12.00	2.50	0.30	9.00	Sq. M	375	
	1	8.00	2.50	0.15	3.00	Sq. M		
	1	3.00	2.50	0.15	1.13	Sq. M		
					76.13	Cum	1939.93	147677.17

Add 12% GST = Rs 68.13
 Add 1% L/Cess = Rs 51.88
 Add signorage fee (76.13x1032.00x10%) = Rs 7856.10
 Total = Rs 174731.30

17721.26 12073.49
 1476.77 1006.12
 7856.10 5354
 174731.30 119046.05

Say 119046 = 00

[Signature]
 JE
 RWD
 Madhawapur

AE
 RWD
 Madhawapur

[Signature]
 EE
 RWD
 Benipatti

checked & Verified for work = 51.8843

[Signature]
 20.12.21
 J-E

[Signature]
 20/12/21
 A.E.

[Signature]
 20/12/21

पत्रांक 492 दिनांक 28/03/22 कार्डपालक अभियंता दरभंगा-2 के जॉय के आधार पर Technically sanctioned for Rs 119046 = 00 (Rupee one lac ninety thousand forty six only)

[Signature]
 Superintending Engineer
 RWD Work Circle, Darbhanga
 Abhinav
 11/05/22