

Inspection Report for Flood Damaged Work in the year 2021-22

Date of Inspection :- 20.12.21 Name of PIU :- RWD (W) Div. *Darbhanga-2*
Name of Block :- HARLAKHI
Name of Road :- TO3 to WEST TOL
For Road :-

1. Damage Location/ Chainage :- CH-0.100KM to CH-0.300KM

2. Damage Length :- 11m

3. Nature of Damage :- Pot holes

4. Details of Restoration Works :- 7.5m³

i. Material being used in Restoration Works Brick Bats

ii. Equipment's/ Tools being used in Restoration Works Roller and Gractor

iii. Procedure taken up in Restoration Works Filling and Compaction

iv. Restored Length : 11m

Remarks :- Work found satisfactory

[Signature]
20.12.21
Signature of JE/AE

[Signature]
20/12/2021

[Signature]
20/12/21
Signature of E.E

[Red Stamp]
प्राप्त 19/12/2021

Name of Road: T03 to West Tol

Block : HARLAKHI District: MADHUBANI

Length : 1.264 KM

Sr No.	Item	Item of Work	Nos	Length (M)	Width (M)	Depth (M)	Quantity	Unit	Rate	Amount
1	1.1	Labour for lying dry graded jhama khoa or Stone filter under Brick pitching or Boulder Pitching in slope or apron including light ramming etc. all complete as per approved design, specification and direction of E/I								
		CH-0.100KM	3	2.000	1.500	0.300	2.70			
		CH-0.300 KM	1	2.000	3.000	0.300	1.80			
		CH-0.300 KM	1	3.000	2.000	0.750	4.50			
						Total	-9.00	CUM	1939.93	-17459.37

Add GST 12% Rs= 2095.12

Add Labour Cess 1% Rs= 174.59

Add Signorage Fee (9.00 x 1032 x 10%) Rs= 928.80

Total Rs= 20657.89

[Signature]
20/11/21
JE
RWD HARLAKHI

[Signature]
20/11/21
AE
RWD HARLAKHI

[Signature]
20/11/21
EE
RWD BENIPATTI

check & verified for qty = 7.50 M³

[Signature]
20.12.2021
J.E.

[Signature]
20/12/2021
A.E.

[Signature]
20/12/21

पत्रांक 492 दिनांक 28/03/22 कार्यपालक अभियंता दरभंगा-2 के जॉय के आधार पर
Technically sanctioned for Rs 17,214=00 (hyper Seventeen thousand
two hundred fourteen only)

[Signature]
Superintending Engineer:
RWD Work Circle, Darbhanga

[Signature]
11/05/22