

Inspection Report for Flood Damaged Work in the year 2021-22

Date of Inspection :- 20.12.21 Name of PIU :- RWD (W) Div. *Janbhangra-2*

Name of Block :- BENIPATTI

Name of Road :- DAMODARPUR PMGSY ROAD TO PASWANI TOLA
VIA BRAHMANI TOLA

For Road :-

1. Damage Location/ Chainage :- CH 0.500 KM to CH 0.800 KM

2. Damage Length :- 199.35m

3. Nature of Damage :- Breaches & Pot holes

4. Details of Restoration Works :- 60.881 m³

i. Material being used in Restoration Works Brick Bats

ii. Equipment's/ Tools being used in Restoration Works Roller and Tractor

iii. Procedure taken up in Restoration Works Filling & Compaction

iv. Restored Length : 199.35m

Remarks :- Satisfactory

[Signature]
20.12.21
Signature of JE/AE

[Signature]
20/12/21
Signature of E.E

Damodarpur PMGSY
Road to Paswan Tol
Via Brahman Tol

Name of Road:

Block : BENIPATTI District: MADHUBANI Length : 1.243 KM

Sr No.	Item	Item of Work	Nos	Length (M)	Width (M)	Depth (M)	Quantity	Unit	Rate	Amount
1	1.1	Labour for lying dry graded jhama khoa or Stone filter under Brick pitching or Boulder Pitching in slope or apron including light ramming etc. all complete as per approved design, specification and direction of E/I								
		CH 0.500 to 0.800 Km	1	3.00	1.50	0.10	0.450			
			1	1.45	0.60	0.15	0.131			
			1	5.00	1.25	0.20	1.250			
			1	7.50	3.00	0.13	2.813			
			1	8.50	3.30	0.13	3.506			
			1	3.30	0.85	0.10	0.281			
			1	7.50	0.50	0.10	0.375			
			1	7.20	1.00	0.13	0.900			
			1	5.50	2.90	0.13	1.994			
			1	18.00	3.00	0.30	16.200			
			1	4.50	0.80	0.15	0.540			
			1	22.50	1.50	0.25	8.438			
			1	9.00	0.90	0.13	1.013			
			1	6.50	1.50	0.15	1.463			
			1	7.50	1.75	0.13	1.641			
			1	1.00	0.90	0.10	0.090			
			1	4.50	1.20	0.10	0.540			
			1	5.50	2.65	0.13	1.822			
			1	3.00	1.00	0.13	0.375			
			1	6.90	0.50	0.08	0.259			
			1	6.20	3.50	0.23	4.883			
			1	7.20	1.65	0.15	1.782			
			1	7.10	1.60	0.15	1.704			
			1	7.50	1.10	0.23	1.856			
			1	14.00	1.20	0.38	6.300			
			1	1.50	0.75	0.15	0.169			

		2	0.50	0.95	0.15	0.143			
		1	7.50	1.00	0.23	1.688			
		1	2.00	1.70	0.15	0.510			
		1	10.00	1.50	0.30	4.500			
		Total		199.35		67.611	Cum	1939.93	118104.87
		Total							
		Add GST 12% Rs=						15739.21	14172.0
		Add Labour Cess 1% Rs=						1311.60	11810.9
		Add Signorage Fee (67.611x1032x10%) Rs=						6977.43	6282.8
		Total Rs=						155188.37	139741.32

[Signature]
20/11/21
JE
RWD BENIPATTI

[Signature]
20/11/21
AE
RWD BENIPATTI

[Signature]
20/11/21
EE
RWD BENIPATTI

checked & Verified for $60.881 M^3$

[Signature]
20.12.21
A.E.

[Signature]
20/12/21
A.E.

[Signature]
20/12/21

प्रमाणित 492 दिनांक 28/03/22 कार्यपालक अभियंता दरभंगा-2 के जांच के आधार पर

Technically sanctioned for Rs 1,39,741.00 (Rupees one lac thirty nine thousand seven hundred forty one only)

[Signature]
Superintending Engineer
RWD Work Circle, Darbhanga
Abhinav
11/05/22