

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग कार्य प्रमंडल बांका-1

पत्रांक 1240 अशु0

बांका/ दिनांक 19.07.2022

प्रेषक,

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल बांका-1

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव
बिहार ग्रामीण पथ विकास अभिकरण पटना।

विषय:- New Maintenance Policy 2018 (MR 3054) योजना अन्तर्गत आवंटन के संबंध में।

महाशय,

उपर्युक्त विषयक से संबंधित एम0आर0 योजना अन्तर्गत संवेदक द्वारा कराए गये कार्यों के भुगतान हेतु विहित प्रपत्र में अधियाचित राशि रूपया 62.88000 लाख का आवंटन उपलब्ध कराने की कृपा की जाय। ताकि संवेदक को भुगतान किया जा सके।

- अनु0:-
1. अधियाचना प्रपत्र
 2. IRI Report

विश्वासभाजन


द/-

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल बांका-1।

ज्ञापांक- 1240 अशु बांका,

दिनांक- 19.07.2022


प्रतिलिपि- मुख्य अभियंता-4, ग्रामीण कार्य विभाग, बिहार, पटना को सूचनार्थ एवं आवश्यक कार्रवाई हेतु समर्पित।

 19/7/22

कार्यपालक अभियंता,

ग्रामीण कार्य विभाग,

कार्य प्रमंडल बांका-1।



FORM GFR 19-A
(See Government of India's Decision (I) below Rule-150
Form of Utilization Certificate up to the month 18.07.2022
MR New Policy 2018

PIU - R.W.D. Works Division Banka-1


Sl. No.	Name of Scheme	Sanction No. & Date with Amount (in lacs Rs.)	Amount Received (in Lacs Rs.)	Particulars
1.	Construction of Rural Roads under MR New Policy 2018	CFMS Letter No - 20 WE, Dt- 14.03.2022	6538.32854	Certified that out of Rs. 6538.32854 Lacs received upto the years 2021-22 in favour of Ex. Engineer, RWD Bihar, Banka-1 a sum of Rs. 6538.17063 lacs has been utilized for the purpose of MR New Policy 2018 Schemes as given in the margin for 0.15791 Lacs remaining unutilized at the end of the period under.
	Total		6538.32854	

2. Certified that I have satisfied may self that the conditions on which the grants in aid was sanctioned have been duly fulfilled/ are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kinds of Checks exercised-

- i. Works have been supervised by Executive Engineer/Superintending Engineer
 - ii. Periodical inspection has been conducted by Executive engineer/Superintending Engineer
 - iii. Construction materials have been tested.
 - iv. Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer / Executive Engineer
 - v. All other codal formalities have been observed.
3. Physical Progress achieved-
 - i. Construction of Road Works
 - ii. Construction of C.D. Works


Sr. Divisional Accounts Officer
Work Division
Rural Works Department
Banka 1


Executive Engineer
Work Division
Rural Works Department
Banka-1

Division : Banka-1

Requisition Format for Scheme Head - MR (3054) Under Bihar Rural Road maintenance Policy 2018 (Initial Rectification and Surface Renewal)

Sl No	Package no.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative Approval (AA)		Agreement Amount (in Lac)		Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRL (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in percentage	Previous Total Allotted Amount (Lac)	up to date expenditure as per MIS (in Lac)	Requisition Against work done (in lac)	Remarks
					Length (in km)	Amount (in Lac)	Initial Rectification with Surface Renewal	5 years Routine Maintenance										
1	RM/BA/BAN/20/0010	BANKA-BELHAR ROAD - KALAWARI	20703602010	1098 31.03.2021	2.612	95.752	66.64842	23.29489	01MIBD/20 21-22 28.01.2022	01.01.2023	N.A	2060	25	5%	0.00000	0.00000	62.88000	Physically Completed
Grand Total -																		

Executive Engineer
RWD Works Division
Banka-1
19/11/22

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग कार्य प्रमंडल बांका.-1

Name of Road-

Banka Belhar Road - Kalawari

Name of Scheme -

MR 3054 (New Policy 2018)

Name of Contractor/ Agency -

Narottam kumar Gautam

Length of Road -

2.612 Kms

Project ID -

20703602010

Package No.-

RM/BA/BAN/20/0010


Name of Block -

Belhar


Certified that all item
Wise 100% Measurement
has been taken by me

Certified that all item
Wise 50% Measurement
has been taken by me

Certified that all item
Wise 10% Measurement
has been taken by me


18/07/22
Junior Engineer RWD
Work Section Belhar
Works Division - Banka 1


18/07/22
Assistant Engineer RWD
Work Sub Division
Belhar
Work Division - Banka 1


19/7/22
Executive Engineer
Rural Works Dept.
Works Div.- Banka 1

Road-BANKA-BELHAR ROAD - KALAWARI

Agency Name-NAROTTAM KUMAR GOUTAM

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI mm/km	CATEGORY ROAD	Latitude	Longitude	Event	Y = 0 * X ^ 2 + 0.866 * X + 501.6	Good	Average	Poor
17/7/22	9:46:27	74	0.1	260	0	2600	2753	G	24.92827	86.70747	Normal	X = 2600			
17/7/22	9:47:2	74	0.1	320	20.2	3200	3272	G	24.92919	86.70751	Normal	Y = 2753			
17/7/22	9:47:2	74	0.1	340	10.1	3400	3445	G	24.92993	86.70709	Normal				
17/7/22	9:48:0	74	0.1	360	10.1	3600	3619	G	24.9308	86.70714	Normal				
17/7/22	9:49:22	74	0.1	340	0	3400	3445	G	24.93165	86.70731	Normal				
17/7/22	9:50:0	74	0.1	370	0	3700	3705	G	24.93247	86.70766	Normal				
17/7/22	9:51:0	74	0.1	350	0	3500	3532	G	24.93318	86.70763	Normal				
17/7/22	9:51:8	74	0.1	340	10.1	3400	3445	G	24.93361	86.70687	Normal				
17/7/22	9:51:8	74	0.1	230	30.3	2300	2493	G	24.93444	86.7071	Normal				
17/7/22	9:51:44	74	0.1	340	20.2	3400	3445	G	24.93535	86.70732	Normal				
17/7/22	9:52:0	74	0.1	260	20.2	2600	2753	G	24.93621	86.70756	Normal				
17/7/22	9:52:0	74	0.1	190	30.3	1900	2147	G	24.93704	86.70776	Normal				
17/7/22	9:52:19	74	0.1	170	40.4	1700	1973	G	24.93787	86.70793	Normal				
17/7/22	9:52:19	74	0.1	240	40.4	2400	2580	G	24.9388	86.70779	Normal				
17/7/22	9:52:19	74	0.1	220	30.3	2200	2406	G	24.93964	86.70763	Normal				
17/7/22	9:52:54	74	0.1	210	40.4	2100	2320	G	24.94049	86.70747	Normal				
17/7/22	9:53:0	74	0.1	180	40.4	1800	2060	G	24.94138	86.70737	Normal				
17/7/22	9:53:0	74	0.1	180	40.4	1800	2060	G	24.94229	86.70731	Normal				
17/7/22	9:53:0	74	0.1	180	40.4	1800	2060	G	24.94311	86.70687	Normal				
17/7/22	9:53:29	74	0.1	200	40.4	2000	2233	G	24.94382	86.70645	Normal				
17/7/22	9:53:29	74	0.1	190	40.4	1900	2147	G	24.94468	86.70613	Normal				
17/7/22	9:53:29	74	0.1	180	40.4	1800	2060	G	24.94557	86.7062	Normal				
17/7/22	9:53:29	74	0.1	190	40.4	1900	2147	G	24.94646	86.70646	Normal				
17/7/22	9:54:5	74	0.1	270	30.3	2700	2839	G	24.94709	86.70714	Normal				
17/7/22	9:54:5	74	0.1	250	20.2	2500	2666	G	24.94719	86.70796	Normal				
17/7/22	9:54:5	74	0.1	260	20.2	2600	2753	G	24.94789	86.70859	Normal				

Janit
18/10/22
J.E

18/10/2022
J.E

18/07/22
A.E.

19/7/22
E.E

Name of Customer : NAROTTAM KUMAR GOUTAM
 Name of Work/Road : BELHAR ROAD - KALAWARI
 Lab Job number : 74
 Date : 17-07-2022
 Section No. : 74


Test Date : 17-07-2022 Road Name : BANKA-BELHAR ROAD - KALAWARI
 Machine No : 407 Road Type : (R) RURAL ROAD
 Start S No : Side : Interval :
 Start E No : Weather : Normal UV Range : 9.33 To 5000 1000 mm/Km
 Start Location : Dist Range : 0 To 27 0.1 * 1000 m
 End Location : Equation : $Y = 0.0 * X^2 + 0.866 * X + 501.6$

Print Generate Report and Graph

Redraw Graph

Map View

File : D:\narottam kumar belharnarottam kumar bankal.xls, Section No. : 74, Eqn : $Y = 0.0 * X^2 + 0.866 * X + 501.6$
 Name of Customer : NAROTTAM KUMAR GOUTAM, Name of Work/Road : BANKA-BELHAR ROAD - KALAWARI.



Damit
18/07/22
 A.E.

Narottam
18/07/2022
 J.E.

Damit
18/7/22
 A.E.

19/7/22
 EE