

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>First & Final Bill</u>					
<u>Name of Work - Restoration for Tejpura</u>					
<u>Panchayat Gharoon & Gharwala</u>					
<u>(Kamla Kaur Rai ke Gharwala)</u>					
<u>Name of Agency - Sd/ Ajay Kumar</u>					
<u>Agg. No 85/GTSHY/PDR/SDD/2021-22</u>					
<u>Date of Commencement - 08.02.22</u>					
<u>Date of Completion - 07.03.22</u>					
<u>Date of Party - 28.01.22</u>					
<u>Date of Actual Completion - 28.1.22</u>					

<u>Item of Work</u>					
<u>Sto. 1 -</u>	<u>Construction of Subgrade and earthwork</u>				
	<u>in shoulder ab. abt.</u>				
	2x	9x	30x	0.70+0.08	0.30 = 111.784
	3.4002 = Constant of granular				
	Sub base & base layer				
	well graded at - 100.				
	2x	30x	3.75x	0.10 =	22.50
	2x	30x	3.75x	0.15 =	33.75
	3x	30x	3.75x	0.10 =	33.75
	2x	30x	3.75x	0.075 =	16.875
	106.875				

Continuation

Maximal effort:

- 2

Chlorophyll *a* and *b* content