

Inspection Report for Flood Damage Work

Date :- 30.4.22

Name of PIUs :- R.N.D. Pj. Kalyanpur


Name of Block/ Road :- REO Rajpura well - to Chankabala.

(A) For Road :

1. Damage Location/ Chainage :- 300 to 400, 700 to 750, 900 to 1000, 1100, 1300, 1400, 1800, 1900, 2500,
2. Damage Length :- 93.0m
3. Nature of Damage :- Shoulder cutting & Pot
4. Details of Restoration Works :-
 - (i) Material being used in Restoration Works :- Brick Bat.
 - (ii) Equipment's/ Tools being used in Restoration Works :- Tractor
 - (iii) Procedure taken up in Restoration Works :- 84.215 m³
 - (iv) Restored Length :- 93.0m

(B) For Bridge :

1. Damage Location/ Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration Works :-
 - (ii) Equipment's/ Tools being used in Restoration Works :-
 - (iii) Procedure taken up in Restoration Works :-
 - (iv) Restored Length :-


30/04/22
JE

Signature of JE /AE/EE

— "S" —



Signature

(Name of Inspection)

FOR

REO ~~Rao~~ Raiyam west Chankakalal

Shedule XLV Form No. 134.

Tham Tharpu

DIVISION

Tham Tharpu

SUB-DIVISION

3083

Measurement Book

Name of Work—
 Situation of Work—
 Agency by which work is executed—
 Date of Measurement—
 No. and date of agreement

(These four lines should be repeated at the commencement of the measurement relating to each work)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
C.H. - FDR					
Name of work :- Matsabla of the Road					
from REO Raiyom west					
Chankablat.					
Agency - Departmental.					
Date of entry :- 10.5.22					

Continuation

[illegible]

Continuation

$$\frac{\text{vineyK}}{10.05.00}$$