

Inspection Report of Flood Damage Work

Name of PIUs :- RWD Works Division, Jhanjharpur

Name of Block :- Jhanjharpur

Name of Road :- Movable of Road from Hainrithi to Mahinathipur
Paswan Tol Under FDR.

A. For Road


1. Damage Location Chainage :-
2. Damage Length :- 86.00m
3. Nature of Damage :-
4. Details of Restoration Works
 - i. Materials being used in restoration works:- Bridge bents
 - ii. Equipment's/Tools being used in Restoration works:-
 - iii. Procedure taken up in Restoration works:- 90.45 m
 - iv. Restored Length:-

B. For Bridge

1. Damage Location Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works
 - i. Materials being used in restoration works:-
 - ii. Equipment's/Tools being used in Restoration works:-
 - iii. Procedure taken up in Restoration works:-
 - iv. Restored Length:-

C. Requirement Of New CD/ Bridges

- i. Name of Road:-
- ii. Location/ Chainage:-
- iii. Type of CD Work/ Length required:- 3"


25/04/22

Signature of JE/AE/EE


303E,
24/4/22
RE


25/4

Signature
(Name of Inspection)

MAITHI TO MAHINATH PUR PASWAN TOL. (F.D.R.)

Schedule XLV-Form No. 134

Thantihar pur DIVISION

Thantihar pur SUB-DIVISION

3084

MEASUREMENT BOOK

Name to work—

Situation of work—

Agency by which work is executed—

Date of measurement—

No. and date of agreement.

(These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
C.H:- F.P.R.					
Name of work:- Mostable of road damaged road from Hailki to Madimalkpur Paswan tal ward V.F.P.R.					
Axerog- Departmental					
Date of entry:- 10.5.22					
		work done			
		Measurement as per T/S			
(1) providing and fitting brick batty ridgestakes and damaged embankment including of cost of brick batty and labour charge as per E/L:					
CH-100-250	1X	16.00X	3.00X	0.60	28.80M ³
	1X	19.00X	3.00X	0.45	25.65 "
	1X	15.00X	3.00X	0.45	20.25 "
	1X	15.00X	3.00X	0.35	15.75 "
					90.45M ³
		SHE			
		10.5.22			
				niraj kumar	
				10.5.22	
				AT	

Continuation

Sch. XLV—Form No. 134

Sch. XLV—Form No. 134					Contents of area
Particulars	Details of actual measurement				
	No.	L.	B.	D.	
ABSTRACT OF COST					
(1) provisions and tilings					
brick batts and tiles					
and damaged embankment					
cost including					
cost of brick batts and					
labour charge as per					
E/R					
Qty vide T.M.B.D. (1)					
90.45 m ³ @ 2004-96/m ³					181349-00
Add 12% B.S.T.					21762-00
Add 1% L.C.					1813-00
Add 10% S.P.					9334-00
(90.45 x 1032) x 10%					9615-00
					/

R.D. 214258-00

T.B. 214539-00

~~10.5.22~~

S.E.

~~10.5.22~~
 10.5.22
 A.E.