

Inspection Report of Flood Damage Work

Name of PIUs :- RWD Works Division, Jhunjharpur

Name of Block :- Jhunjharpur

Name of Road :- NH 57 Navar Path to Khalka Tel

A. For Road


1. Damage Location Chainage :- 0-100, 200-250, 300-350 m
2. Damage Length :- 114 m
3. Nature of Damage :-
4. Details of Restoration Works :-
 - i. Materials being used in restoration works:- Brick Ball
 - ii. Equipment's/Tools being used in Restoration works:- Tractor - Trolly
 - iii. Procedure taken up in Restoration works:- 150-100 m
 - iv. Restored Length:- 114 m

B. For Bridge

1. Damage Location Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - i. Materials being used in restoration works:-
 - ii. Equipment's/Tools being used in Restoration works:-
 - iii. Procedure taken up in Restoration works:-
 - iv. Restored Length :-

C. Requirement Of New CD/ Bridges

- i. Name of Road:-
- ii. Location/ Chainage:-
- iii. Type of CD Work/ Length required:-


Signature of JE/AE/EE


20/4/22
BR


Signature
(Name of Inspector)

Name of Work—
Situation of Work—
Agency by which work is executed—
Date of Measurement—
No. and date of agreement

(These four lines should be repeated at the commencement of the measurement relating to each work)

[illegible]

Continuation

Continuation

mark
10.05.20
AE

NH 57 NARUAPATH TO KHATBE TOLA (FDR)

Schedule XLV Form No. 134.

Thanthanpur DIVISION

Thanthanpur SUB-DIVISION

3066

Measurement Book