

Inspection Report of Flood Damage Work

Name of PIUs :- RWD Works Division, Jhanjharpur

Name of Block :- Jhanjharpur

Name of Road :- NH-57 Chauragang - Kanikpur

A. For Road

1. Damage Location Chainage :- 0 to 30 m
2. Damage Length :- 18 m
3. Nature of Damage :-
4. Details of Restoration Works
 - i. Materials being used in restoration works:- Brick-bats
 - ii. Equipment's/Tools being used in Restoration works:- tractor-trolley
 - iii. Procedure taken up in Restoration works:- 46.67 m
 - iv. Restored Length:- 18 m


B. For Bridge

1. Damage Location Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works
 - i. Materials being used in restoration works:-
 - ii. Equipment's/Tools being used in Restoration works:-
 - iii. Procedure taken up in Restoration works:-
 - iv. Restored Length:-

C. Requirement Of New CD/ Bridges


- i. Name of Road:-
- ii. Location/ Chainage:-
- iii. Type of CD Work/ Length required:-

"S"


25/04/22
18

Signature of JE/AE/EE


20/4/22
RR


25/4/22
Signature
(Name of Inspection)

FDR - NH57 Channarayana - Katak Pura

Schedule XLV-Form No. 134

Thanthapur DIVISION

Thanthapur SUB-DIVISION
3074

MEASUREMENT BOOK

[illegible]
$$\begin{array}{r} 18.30 \\ \times 1.3 + 1.57 \\ \hline 20.30 + 0.15 \end{array}$$
$$6.80 \times 3.92 = 0.6704$$