

Inspection Report of Flood Damage Work

Name of PIUs :- RWD Works Division, Jhanjharpur

Name of Block :- Lakhnau

Name of Road :- Lauha To Belaucha

A. For Road

1. Damage Location Chainage :- 0+200, 200-600, 800-2000

2. Damage Length :- 337.0 m

3. Nature of Damage :- Flood.

4. Details of Restoration Works

i. Materials being used in restoration works:- Brick Bats

ii. Equipment's/Tools being used in Restoration works:- Tractor, Back hoe loader

iii. Procedure taken up in Restoration works:- 246.3585

iv. Restored Length:- 337.0 m

B. For Bridge

1. Damage Location Chainage :-

2. Damage Length :-

3. Nature of Damage :-

4. Details of Restoration Works

i. Materials being used in restoration works:-

ii. Equipment's/Tools being used in Restoration works:-

iii. Procedure taken up in Restoration works:-

iv. Restored Length:-

C. Requirement Of New CD/ Bridges

i. Name of Road:-

ii. Location/ Chainage:-

iii. Type of CD Work/ Length required:-

Signature of JE/AE/EE

RA
28/4/22
J-E

3036
24/4/22
BB

Signature
(Name of Inspection)

LAF A TO BELAUCHA ROAD (F.D.R.)

Schedule XLV-Form No. 134

F.D.R - 2021 - 2022

DIVISION

LAKHTAUR.

SUB-DIVISION

MEASUREMENT BOOK

3047

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
CH--	F.D. R.				
Name of work	Mortable of floor damaged road from Lahla to Belahm				
	for road under F.D.R.				
Agency	Departmental				
Date of entry	8/5/2022				
(1)	Poonchi and walking barile batty midstrel and				

						damaged embankment
						including cost of bridge
						batts and labour charge
						as per E/R
CH-0-200M	1x	90.00x	4.00x	$\frac{0.10+0.15}{2}$		99.00 M ³
	1x	34.00x	2.00x	0.125		8.50
	1x	7.00x	2.00x	0.125		1.75
	1x	2.00x	2.00x	0.125		0.50
	1x	2.00x	2.00x	0.125		0.50
	1x	3.00x	2.00x	0.125		0.7875
	1x	15.00x	3.00x	0.125		5.625
CH-200-600M	1x	4.00x	2.80x	0.15		1.68
	1x	6.00x	3.20x	0.125		2.40
CH-200-600M	1x	2.00x	2.00x	0.125		0.50
"	1x	4.00x	2.80x	0.10		1.12

Continuation

[illegible]

[illegible]

Scanned with CamScanner