

BLOCK :- Jhanibaraur
KAKO TOOSHALL (F.D.R.)

Shedule XLV Form No. 134.

Jhan Jhanbar DIVISION

Jhan Jhanbar SUB-DIVISION

3072

Measurement Book

Scanned with CamScanner

Scanned with CamScanner

Inspection Report of Flood Damage Work

Name of PIUs :- RWD Works Division, Jhanjharpur

Name of Block :- Jhanjharpur

Name of Road :- Kaka to Ajhau

A. For Road


1. Damage Location Chainage :- 3200-3400, 3400-3600
2. Damage Length :- 122 M, + 188.30 = 311.30 M
3. Nature of Damage :-
4. Details of Restoration Works
 - i. Materials being used in restoration works:- Brick bats
 - ii. Equipment's/Tools being used in Restoration works:- By Tractor-Trolley
 - iii. Procedure taken up in Restoration works:-
 - iv. Restored Length:- 178.184 m³


B. For Bridge

1. Damage Location Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works
 - i. Materials being used in restoration works:-
 - ii. Equipment's/Tools being used in Restoration works:-
 - iii. Procedure taken up in Restoration works:-
 - iv. Restored Length:-

C. Requirement Of New CD/ Bridges

- i. Name of Road:-
- ii. Location/ Chainage:-
- iii. Type of CD Work/ Length required:- — 3" —


Signature of JE/AE/EE


20/4/22
RR


Signature
(Name of Inspection)