

L052-L021 RED ROAD TO PASWAN TOLA (VRO52) (F.D.R.)
F. D. R. 2021-2022

Schedule XLV-Form No. 134

LAKHANAU

DIVISION
SUB-DIVISION

MEASUREMENT BOOK

3043

Name of Work--
 Situation of Work--
 Agency by which work is executed--
 Date of Measurement--
 No. and date of agreement

(These four lines should be repeated at the commencement of the measurement relating to each work)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
CH. - F.P.R.					
Name of work -	Mortable of flood damaged				
	road from L052-L021 RCO				
	road to Pakhigatla				
	under F.P.R.				
Agency -	Departmental				
Date of entry -	8/5/2022				
(1) provisions and fittings					
bridge battis in pithor and					
damaged embankment					
including cost of bridge					
battis and latah road					
as per E/I					
CH-0-2235M-	1x	30.00x	4.20x	0.30	37.80M ³
	1x	27.00x	4.35x	1.00	117.451
	1x	30.00x	4.80x	0.30	43.2011
	1x	5.00x	0.50x	0.25	0.62511
	1x	7.00x	0.50x	0.25	0.87511
					199.95M ³

Continuation

7.
Name of Work-
Situation of Work-
Agency by which work is executed-
Date of Measurement-
No. and date of agreement

(These four lines should be repeated at the commencement of the measurement relating to each work)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
CH. - F.P.R.					
Name of work -	No. table of flood damage				
	road from L052-L021 RCO				
	road to Padwa talga				
	under F.P.R.				
Agency -	Departmental				
Date of entry -	8/5/2022				
(1) providing and fixing					
brake batts in distal end					
damaged embankment					
including cost of brake					
batts and labour charge					
as per E/I					
CH-0 - 2235M -	1x	30.00x	4.20x	0.30	37.80M ³
	1x	27.00x	4.35x	1.00	117.451
	1x	30.00x	4.80x	0.30	43.2011
	1x	5.00x	0.50x	0.25	0.62511
	1x	7.00x	0.50x	0.25	0.87511
					199.95M ³

Continuation

2

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
				BF	199.95M ³
1. 8/5/2022				AE	

Inspection Report of Flood Damage Work

Name of PIUs :- RWD Works Division, Jhanjharpur

Name of Block :- Lakhnaur

Name of Road :- L052 - L021 REO ROAD TO PASWAN TOLA (VR052)

A. For Road

1. Damage Location Chainage :- 0 to 2.235 KM.

2. Damage Length :- 0.179 KM

3. Nature of Damage :-

4. Details of Restoration Works

i. Materials being used in restoration works:-

Brick - Bal's

ii. Equipment's/Tools being used in Restoration works:-

Tractor & JCB.

iii. Procedure taken up in Restoration works:- 199.95

iv. Restored Length:- 0.179 KM.

B. For Bridge

1. Damage Location Chainage :-

2. Damage Length :-

3. Nature of Damage :-

4. Details of Restoration Works

i. Materials being used in restoration works:-

ii. Equipment's/Tools being used in Restoration works:-

iii. Procedure taken up in Restoration works:-

iv. Restored Length:-

C. Requirement Of New CD/ Bridges

i. Name of Road:-

ii. Location/ Chainage:-

iii. Type of CD Work/ Length required:-

Signature of JE/AE/EE

27/04/2022
J.E.

3036
23/4/22
RR
27/04/2022

Signature
(Name of Inspection)