PMGSY TO MUSHAHRI BELAUNCHA (P-D.R.)
F.D.R- 2021-2022

Schedule XLV-Form No. 134

Executive Engineer
Rural Works Department
Works Division, Jhanjharpur

_____ DIVISION

LAKHNVAR _____ SUB-DIVISION

1923

MEASUREMENT BOOK

Scanned with CamScanner

Name of work—
Situation of work—
Agency by which work is executed—
Date of measurement—
No. and date of agreement
(These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents or area
	No.	L	B	D	
CH:-	F. D. R.				
Name of work-	Metalling & Hardening				
	and Improvement to				
	Mallalam Belakkody				
	under F.D.R.				
Agency-	Departmental				
Date of entry-	8/5/2022				
(1)	Providing and fitting				
	bricke batts in dilapidated and				
	damaged embankement				
	including cost of brick				
	batts and labour charge				
	as per EH				
CH-0-200M	1	30.00	$\frac{0+37+0.5}{2}$	0.54	6.48 M³
	1	5.50	0.40	0.54	1.188 "
	1	30.00	0.40	0.54	6.48 "
	1	30.00	0.40	0.54	6.48 "
	1	30.01	0.15	0.15	0.675 "
	1	15.01	0.20	0.25	0.75 "
CH-200-400M	1	30.00	0.20	0.20	1.20 "
					23.253 M³

8/5/22

Continuation

8/5/22
AE

Scanned with CamScanner

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	ABSTRACT OF COST.				
(1)	Providing and filling brick batty in dutch & and damaged embankment including cost of brick batty and labour charge as per E/I				
	Qty vide T.M. BP-1(1)				
	23.253 m^3 @	200/- = 96/m^3			4662/33
	Add 12% COST.				559/56
	Add 1% L.C.				46621
	Add 10% S.F.				2399/70
				T.A	55081/81
				Say	55082/-

8/5/2021
AE

8/5/2021
AE

Scanned with CamScanner

Inspection Report of Flood Damage Work

Name of PIUs :- RWD Works Division, Jhanjharpur

Name of Block :- Laukahi

Name of Road :- Pipra to Mushahari (Bochaha)

A. For Road

1. Damage Location Chainage :- 0-200, 200-400
2. Damage Length :- 361.0 M
3. Nature of Damage :- Flood
4. Details of Restoration Works
   i. Materials being used in restoration works:- Brick bats
   ii. Equipment's/Tools being used in Restoration works:- Tractors
   iii. Procedure taken up in Restoration works:- 23.253 m3
   iv. Restored Length:- 361.0 M

B. For Bridge

1. Damage Location Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works
   i. Materials being used in restoration works:-
   ii. Equipment's/Tools being used in Restoration works:-
   iii. Procedure taken up in Restoration works:-
   iv. Restored Length:-

C. Requirement Of New CD/ Bridges

i. Name of Road:-
ii. Location/ Chainage:-
iii. Type of CD Work/ Length required:-

Signature of JE/AE/EE

24/12

28/04/2022
S.E

Signature
(Name of Inspection)

Scanned with CamScanner