

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, डिहरी

पत्रांक 559 3730

डिहरी / दिनांक 06/06/2022

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, डिहरी

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी —सह—सचिव,
ब्राडा,
भूमि विकास बैंक भवन,
बुद्ध मार्ग, पटना।

विषय :- MR New Maintenance policy-2018 में किये गये कार्य के विरुद्ध
आवंटन उपलब्ध कराने के संबंध में।

महोदय,

उपरोक्त विषय के संबंध में सूचित करना है कि MR New Maintenance policy-2018 अर्न्तगत कराये गये कार्यों के विरुद्ध संवेदक को भुगतान करने हेतु अधियाचना विहित प्रपत्र में भरकर आवश्यक कार्यवाही हेतु समर्पित की जाती है। इस पथ में कोई भी ATR लंबित नहीं है। उक्त पथ का सही डाटा की प्रविष्टि MIS पर अद्यतन है।

अनु :- यथोक्त।

विश्वासभाजन

NKumar
06.06.22

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, डिहरी

NKb
06/06/2022

FORM GFR 19 -A

(SEE GOVERNMENT of India's Decesion (I) below Rule - 150)
Forms of Utilisation Certificate upto the Month of November 2021
NEW MAINTENANCE POLICY 2018 MR (3054) MAINTANANCE

PIU - RWD DEHRI

S.No	Name of Scheme	Sanction No. & Date	Amount Received	Particulars
		With amount(in Rs. Lacs)	(In Rs. Lacs)	
1	Contruction of Rural Road under MR-03054	51 30.04.2022	12.68526	Certificate that out of Rs. 12.68523 Lacs received during the years in favour of Executive Engineer , RWD Dehri Bihar. Sum of Rs. 0 Lacs has been utilised for the purpose of MR (3054)-2018 Fund hences as given in the margin for which it was sanctioned and that the balance of Rs. 12.68526 Lacs remaining unutilized at the end of the period under.
TOTAL			12.68526	

Certified that I have satisfied myself that the conditions on which the grand-in-aid was sanctioned have been duly fulfilled / are being fulfilled and that I have exercised the following checks to see that the money was actually utilized

for the purpose for which it was sanctioned.

Kind of Checks exercised :-

- Works have been supervised by Executive Engineer / Supertending Engineer.
- Periodical inspeioin has been conducted by Executive Engineer / Supertending Engineer.
- Construction materials have been tested.
- Measurements have been recorded in the MBs and test check conducted by the Assistant.
- All other codal formalities have been observed.

3 Physical Progress achieved :-

- Construction of Road works.
- Construction of CD works.

[Signature]
D.A. 06/06/22

RWD (W) Div. Dehri

[Signature]
06.06.22

Executive Engineer
RWD (W) Div. Dehri

[Signature]
06/06/2022

Office of the Executive Engineer, Rural Works Department, Works Division, Dehri
Requisition formate Scheme Head MR (3054) under Bihar road Maintenance Policy-2018 (Rectification and Surface Renewal)

No.	Package No	Name of Road	Project Id as per MIS	Administrative Approval (AA) Letter No. and Date	Administrative Approval (AA)		Agreement (in Lakh)		Agreement No. and Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/KM)	Thickness of Bitumin Layer (in mm)	Value of Bitumin Content in Percentage	Previous total amount (in Lakh)	Up to Date expenditure as per MIS (in Lakh)	Requisition against Work Done (in Lakh)	Remarks
					Length (in Km)	Amount (in lakh)	Initial Rectification on with Surface Renewal (in Lakh)	Five Year Routine Maintenance (in Lakh)										
1																		
2																		
3																		
4																		
5																		
6																		
7																		
8																		

विभागीय पत्रांक-मु0380(सु) 3054-4-04/2020 पार्ट 4 5047 दिनांक 23.12.2021 के आलेख में प्रमाणित किया जाता है कि-

1. गुणवत्ता पूर्ण एवं विशिष्टियों के अनुरूप कार्य कराने के बाद MIB में दर्ज किया गया है।

2. सम्बन्धित कार्य कमीय अभियंता द्वारा कराया गया (100% जांचा गया) सहायक अभियंता द्वारा 50% तथा कार्यपालक अभियंता द्वारा 10% जांचा गया तथा MIS पर Upload किया गया।

[Signature]
 D.A.O
 RWD (W) Div. Dehri

[Signature]
 06.06.22
 EXECUTIVE ENGINEER
 RWD, WORKS DIVISION,
 DEHRI

[Signature]
 06/06/22

Road Name-P.W.D. Path to Sone Nadi tak Samahuta path Nirman

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI mm/km	ROAD CATEGORY	Latitude	Longitude	Event
4/6/22	11:7:0	107	0.1	220	0	2200	2615	G	24.6599	83.99364	Normal
4/6/22	11:7:10	107	0.1	250	20.2	2500	2915	G	24.66036	83.99304	Normal
4/6/22	11:7:10	107	0.1	320	20.2	3200	3615	G	24.66064	83.99225	Normal
4/6/22	11:7:45	107	0.1	270	20.2	2700	3115	G	24.66091	83.99135	Normal
4/6/22	11:8:0	107	0.1	210	10.1	2100	2515	G	24.66105	83.99076	Normal
4/6/22	11:8:20	107	0.1	260	20.2	2600	3015	G	24.66173	83.99084	Normal
4/6/22	11:8:20	107	0.1	290	20.2	2900	3315	G	24.66212	83.98667	Normal
4/6/22	11:9:0	107	0.1	230	10.1	2300	2715	G	24.6621	83.98852	Normal
4/6/22	11:9:31	107	0.1	300	10.1	3000	3415	G	24.66252	83.98743	Speed Breaker
4/6/22	11:9:31	107	0.1	220	20.2	2200	2615	G	24.66295	83.98658	Normal
4/6/22	11:10:6	107	0.1	250	20.2	2500	2915	G	24.66326	83.98608	Normal
4/6/22	11:10:6	107	0.1	260	20.2	2600	3015	G	24.66299	83.98561	Normal

$$Y = 0 * X^2 + 1.000 * X + 415.2$$

$$X = 2900$$

$$Y = 3315$$

(R) RURAL ROAD

Good Average Poor
<4000 4001-5000 >5001

IRI Value

Average IRI-2981.66

204-06-22
J.F.

204-06-22
D.A.E.

204-06-22
D.A.E.

Name of Customer: Bethie Singer

Name of Work/
 Road :
 Lab Job number
 Date :
 Section No.


Test Date:	10/06/2022		Road Name:	main road to Serravallo (p86) Vi	
Machin: No.	411		Road Type:	RURAL ROAD	
Start S. No.			Side:		
Start E. No.:			UV Range:	1515 To 5000	
Wavelength:			Dist Range:	0 To 13	
Start Location:	P-W/D 36th		Equation:	$Y = -0.0002 \cdot X + 4152$	
End Location:	Stone Mouth Rd			Interval 1000 5m/min 1000mm	

Paint	Gonzalez Murguiri and Grehn
-------	-----------------------------

```
File: C:\Users\BRIAN\Desktop\Bilder\simplypdf path to some mail.txt: secret@to path: nimen\PMO PATH: TID
Name of Quantifier: Name of Work Round: Eub Job number:
```

Readings Graph

Map View



280
040622
J.E

MXV
04.06.22
A.E.

04.06.22
EF