

Inspection Report of Flood Damage Work

Name of PIUs :- RWD Works Division, Jhanjharpur

Name of Block :- Lakhanur

Name of Road :- L062- L021 Tamwriya Berma REO Road To Bhakhruli

A. For Road

1. Damage Location Chainage :- 0-600 , 600-1000
2. Damage Length :- 471.0m
3. Nature of Damage :- Flood
4. Details of Restoration Works
 - i. Materials being used in restoration works:- Brick Bats
 - ii. Equipment's/Tools being used in Restoration works:- Tractor
 - iii. Procedure taken up in Restoration works:- 54.261m³
 - iv. Restored Length:- 471.0m

B. For Bridge

1. Damage Location Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works
 - i. Materials being used in restoration works:-
 - ii. Equipment's/Tools being used in Restoration works:-
 - iii. Procedure taken up in Restoration works:-
 - iv. Restored Length:-

C. Requirement Of New CD/ Bridges

- i. Name of Road:-
- ii. Location/ Chainage:-
- iii. Type of CD Work/ Length required:-

Signature of JE/AE/EE

Signature
(Name of Inspection)

L062-L021 TAMUR14A BERM A RED ROAD TO BHAKHRAULI KE-062
(F.P.R.)

Schedule XLV-Form No. 134

F.P.R.-2021-2022

DIVISION

LAKHAPUR

SUB-DIVISION

MEASUREMENT BOOK

3054

Name of work—

Situation of work—

Agency by which work is executed—

Date of measurement—

No. and date of agreement.

(These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Ch-- F.D.R.					
Name of work--	LO 62-LO 21	Tamxinta			
	Bermud	Ed	road to		
	Blakazulu	undir			
	F.D.R.				
Agency--	Departmental				
Date of report--	8/5/2022				

(1) Provision of additions					
bridge batts in distal end					
damaged embankment					
including cost of bridge					
batts and labour charge					
as per E/R					
CH-0-600M	1x	5.00x	1.20x	0.15	0.90m ³
	1x	9.00x	0.50x	0.25	1.125 "
	1x	2.00x	1.10x	0.20	0.44 "
	1x	34.00x	$\frac{1.50+0.50}{2}$	0.20	5.10 "
	1x	32.00x	$\frac{1.50+0.50}{2}$	0.30	9.60 "
11-600-1000M	1x	49.00x	$\frac{0.50+0.20}{2}$	0.5	2.5731
	1x	117.00x	$\frac{0.40+0.50}{2}$	0.30	15.79511
	1x	51.00x	$\frac{0.25+0.40}{2}$	0.20	3.31511
	1x	2.50x	0.40x	0.20	0.20

Continuation

C/O. 39.04111

[illegible]

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
ABSTRACT OF COST.					
(1) provisions and fixtures					
brick batts rubble and					
damaged embankment					
including cost of brick					
batts and labour done					
after E/S					
Qty mtd T.M.B.P. (CU)					
54.261 m ³ @ 2004.96/m ³					108791.13
Add 2% CST.					13054.94
Add 1% L.C.					1087.91
Add 10% S.F.					5599.74
				T.B	128533.72
8/5/2022					
Sub					128534.00
AE					