

Inspection Report of Flood Damage Work

Name of PIUs :- RWD Works Division, Jhanjharpur

Name of Block :- Lakhnau

Name of Road :- NH-57 to Dubourbanana

A. For Road

1. Damage Location Chainage :- 200m, 275 m

2. Damage Length :- 28.50 m

3. Nature of Damage :- Flood

4. Details of Restoration Works

i. Materials being used in restoration works:- Brick Bat

ii. Equipment's/Tools being used in Restoration works:- Tractor, Back hoe loader

iii. Procedure taken up in Restoration works:- 1.68 m³

iv. Restored Length:- 28.50 m

B. For Bridge

1. Damage Location Chainage :-

2. Damage Length :-

3. Nature of Damage :-

4. Details of Restoration Works

i. Materials being used in restoration works:-

ii. Equipment's/Tools being used in Restoration works:-

iii. Procedure taken up in Restoration works:-

iv. Restored Length:-

C. Requirement Of New CD/ Bridges

i. Name of Road:-

ii. Location/ Chainage:-

iii. Type of CD Work/ Length required:-

Signature of JE/AE/EE

Signature
(Name of Inspection)

NH 57 TO DUDHARBAHANA (F.D.R.)

F.D.R. - 2021-2022

Schedule XLV-Form No. 134

Executive Engineer
Rural Works Department
Works Division, Jhanjharpur

DIVISION

LAKHNAR

SUB-DIVISION

1917

MEASUREMENT BOOK

Name of work—

1

Situation of work—

Agency by which work is executed—

Date of measurement—

No. and date of agreement.

(These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
CH— F.P.R.					
Name of work—	Mortable of Flood				
	damaged road width 2.8				
	and damaged embank-				
	ment including cost of				
	bridge batty and labour				
	charge as per E/I				
CH— 200 M	1	7.00	1.20	0.20	1.68 M ³
Agency—	Departmental				1.
					1.68 M ³
Date of entry—	8/5/2022				
CH— 200 M	1	7.00	1.20	0.20	1.68 M ³
	8/5/2022				
	A.P. 1				
	8/5/2022				
	A.E				

Continuation

			Sch 9	3980=00
			8/5/22	AC