

Inspection Report of Flood Damage Work

Name of PIUs :- RWD Works Division, Jhanjharpur

Name of Block :- Lakshnau

Name of Road :- L057 - To NH57 Behat Dip End

A. For Road

1. Damage Location Chainage :- 100, 1100, 2400 m
2. Damage Length :- 57.0 m
3. Nature of Damage :-
4. Details of Restoration Works

- i. Materials being used in restoration works:- Brick Bath
- ii. Equipment's/Tools being used in Restoration works:- Tractor, Back hoe loader
- iii. Procedure taken up in Restoration works:- 18.55 m³
- iv. Restored Length:- 57.0 m

B. For Bridge

1. Damage Location Chainage :-
 2. Damage Length :-
 3. Nature of Damage :-
 4. Details of Restoration Works
- i. Materials being used in restoration works:-
 - ii. Equipment's/Tools being used in Restoration works:-
 - iii. Procedure taken up in Restoration works:-
 - iv. Restored Length:-


C. Requirement Of New CD/ Bridges

- i. Name of Road:-
- ii. Location/ Chainage:-
- iii. Type of CD Work/ Length required:-

Signature of JE/AE/EE


28/04/22
J.E


23/4/22
R.R


Signature
(Name of Inspector)

NH 6057-TOL NH-57-BEHAT DIP EAST (VROST) (F.P.R.)

F.P.R. - 2021-2022

Schedule XLV-Form No. 134

DIVISION

SUB-DIVISION

MEASUREMENT BOOK

3049

Name of Work-

Situation of Work-

Agency by which work is executed-

Date of Measurement-

No. and date of agreement

(These four lines should be repeated at the commencement of the measurement relating to each work)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
CH- -	F.P.R.				
Name of work -	Mostable of flood damage				
	road from LOSI TO L				
	HH 50 TO BE Lalpup				
	CH (VR 05) under				
	F.P.R.				
Agency -	Departmental				
Date of estimate -	8/5/2022				
(1) Providing and laying					
brick batts and stones					
and damaged embankment					
ment including cost					
of brick batts and labour					
charge as per Eff					
CH-100M	1x	7.00x	1.00x	0.20	1.40m ³
	1x	5.00x	1.70x	0.20	1.70 m
	1x	3.00x	1.00x	0.15	0.451
CH-1100M	1x	20.00x	3.00x	0.25	15.00 m
					18.55m ³

Continuation

Scanned with CamScanner

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	ABSTRACT OF COST				
Name of work (H)	Providing and filling				
	single batty niches				
	and damage embleme				
	ment including cast				
	of side batty and labor				
	charge after EF				
	etc vide T.M.B.P. 1 (1)				
	18.55 m ³ @	2004	26/m ³		33/92=0
	Add 12% GST			1	4463=01
	Add 1% L.C.			1	371=92
	Add 10% S.F.			1	1914=36
				T. 01	43941=28
				Sub 1	43941=00
				AE	