

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 4/6/22		District: Munongabad
Division : Saurpurnagar		Length (km): 1.0 KM
Name of the Road: House of Kesho Mahato to Last Yogi's Bigha		
Scheme/Programme: GTSNY		
Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement C.C.	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	S
Observation Remarks:- C.C. surface is in good condition.		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	N.A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S
c)	Condition of railings/slab/approach for Bridges	S
d)	Condition of Vent Clearance	S
Observation Remarks:- R.C.C. culvert is in good condition.		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/4m & 200m stones/Pavement road markings are provided and maintained	S
Observation Remarks:- Road furniture, Informatory and Maintenance board, KM Post 200m Post is fixed in the road.		
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

S

Name of Officer:- Ratnesh Paswan

Designature:- Executive Engineer

(Signature)

E-E

Regional Laboratory
Muzaffarpur