

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 4/6/22		District: Arunachal Pradesh
Division : Sadiya		Length (km): 2.0 KM
Name of the Road: L031-Sadiya L030 to Holi chak		
Scheme/Programme: PMGSY		
Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement B.T. m.c.c.	
a)	Condition of Surfacing B.T	U
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	S
Observation Remarks:- B.T surface is damaged at ch 150 m to 200 m. c.c. surface is in good condition.		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N.A
c)	Condition of railings/slab/approach for Bridges	N.A
d)	Condition of Vent Clearance	S
Observation Remarks:- H-P culvert is in good condition.		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
Observation Remarks:- Road furniture Informatory & maintenance board km Post and 200m Post is fixed in the road.		
4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

1)

Name of Officer:- Ratnesh Paswan

Designation:-

Executive Engineer

22/6/22
 (Signature) 4-6-22