

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 4/6/22		District: Aurangabad
Division : Daulnagar		Length (km): 0.925 KM
Name of the Road: NH 98 to middle school Atauili		
Scheme/Programme: MMGSY (SC)		
Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement B.T & C.C.	
a)	Condition of Surfacing C.C.	U
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	U
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	S
Observation Remarks:- B.T surface is in good condition. C.C. surface is rough and exposed aggregates at ch 350 to 410m.		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NA
c)	Condition of railings/slab/approach for Bridges	NA
d)	Condition of Vent Clearance	NA
Observation Remarks:- N.A.		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
Observation Remarks:- Road furniture, Informatory and maintenance board 1km post and 200m post is fixed on the road.		
4.	Compliance History	
a)	Status of ATR's & any others	-

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

U

Name of Officer:- Ratnes L Pawar

Designature:- Executive Engineer

(Signature) 4-6-22

E - E

R.W.D. Regional Laboratory
Muzaffarpur