

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 4/6/22		District: Aurangabad
Division : Daudnagar		Length (km): 7.35 KM
Name of the Road: NH 98 (Bharupnagar) to Malwa path		
Scheme/Programme: MR (30547)		
Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement B.T & C.C.	
a)	Condition of Surfacing	U
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	U
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	S
Observation Remarks:- C.C. surface is rough exposed - aggregates and B.T surface is damaged at ch 3900M to 4100M, 5200 to 5300M & 6700M to 7000M		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N.A
c)	Condition of railings/slab/approach for Bridges	N.A
d)	Condition of Vent Clearance	S
Observation Remarks:- H.P culvert is in good condition		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
Observation Remarks:- Road furniture, Informatory board re maintenance board, KM Post and 200M Post is fixed in the road		
4.	Compliance History	
a)	Status of ATR's & any others	-

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

U

Name of Officer:- Rakesh Paswan
 Designature:- Executive Engineer

22/4/22
 (Signature)

E.E
 Regional laboratory
 Muzaffarpur