

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 4/6/22		District: Aurangabad
Division : Daulnagar		Length (km): 1.865 KM
Name of the Road: Jiyadi pur to Amar pur		
Scheme/Programme: MMGSY (S)		
Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	U
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N.A
e)	Contraction Joints provided or not (CC Pavement)	N.A
f)	Compaction of flank/slope & raincuts if any	S
Observation Remarks:- B-T surface is damaged at ch- 18m to 20m.		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S
c)	Condition of railings/slab/approach for Bridges	S
d)	Condition of Vent Clearance	S
Observation Remarks:- H-P. culvert and R.C.C. culvert is in good condition.		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
Observation Remarks:- Road Furniture, Informatory and Maintenance board km post and 200m post is fixed in the road.		
4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

U

Name of Officer:- Ratnesh Paswan
 Designation:- Executive Engineer

22/5/2022
 (Signature) 4-6-2022

E.E.
 R.W.D. Regional Laboratory
 Muzaffarpur