

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 8/06/2022		District: ROHTAS
Division : BIKRAMGANJ		Length (km): 1.675 km
Name of the Road: BIKRAMGANJ NATWAR PWD ROAD TO MAIDHARA TO BAHUARA-KA SESH BHAG.		
Scheme/Programme: MMGSY		
Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	-
e)	Contraction Joints provided or not (CC Pavement)	-
f)	Compaction of flank/slope & raincuts if any	S
Observation Remarks:-		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	-
c)	Condition of railings/slab/approach for Bridges	-
d)	Condition of Vent Clearance	S
Observation Remarks:-		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
Observation Remarks:-		
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

SATISFACTORY

Name of Officer:- Sri Kant Prasad.

Designature:- E.E.

Vikash Kumar
8/6/2022
AE

(Signature)

8/6/2022
F.S Mo- 7.



Latitude: 25.230114
Longitude: 84.180768
Elevation: 88.33±6 m
Accuracy: 11.0 m
Time: 08-06-2022 11:59

Note: RWD, Bikramgunj division, MMGSY, Bikramgunj Natwar PWD path se maidhra se bahuara ka sesh bhaag

Powered by NoteCam



Latitude: 25.234691
Longitude: 84.183987
Elevation: 93.35±3 m
Accuracy: 10.7 m
Time: 08-06-2022 12:02

Note: RWD, Bikramgunj division, MMGSY, Bikramgunj Natwar PWD path se maidhā se bahuāra ka sesh bhaag

Powered by NoteCam