

# Schedule XLV-Form No. 134

1029 - Kuxson To Tengxi

Jhan Jharpor

DIVISION

Madhapor

SUB-DIVISION

2095

MEASUREMENT BOOK



# INDEX

# PAGE

प्रेमापति विभा जाना है की  
 कल मायी-पुस्तक में मशीन  
 डाल अंकित 1000 पन्ना है  
 जहाँ की-लिखत अंकित है  
 मन्त्रपुर की विविध विभा-  
 जाना है

3636  
 22/4/22

कार्यपालक अभियंता  
 ग्रामीण कार्य विभाग  
 जंझारपुर  
 22/4/22



1

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	


① Providing and filling brick bats

Day 5	35.70 m <sup>3</sup>
-------	----------------------

SAHYS  
07/05/022  
JL

Scanned with CamScanner



Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Abstract of cost					
providing and filling					
brick bats					
35.70 m <sup>3</sup> @ 4.7 MBP - (1)					
@ 2004.96 / m <sup>3</sup> — 1871577.07					
1871577.07					
Add 12% cost (F) RS. 8589.25					
Add 1% L.C.E.S.S (P) RS. 715.77					
Add 10% S.Fee (P) RS. 3684.24					
RS. 84566.33					
Say RS. 84566.00					
 7/5/22 AG					MANUS 07/05/22 J.E

[illegible]



# Inspection Report of Flood Damage Work

Name of PIUs :- RWD Works Division, Jhanjharpur

Name of Block :- Machhapur

Name of Road :- L029 - Kusan to Tongri

## A. For Road

1. Damage Location Chainage :- 450m, 0
2. Damage Length :- 34m
3. Nature of Damage :-
4. Details of Restoration Works
  - i. Materials being used in restoration works:- Brick bats
  - ii. Equipment's/Tools being used in Restoration works:-
  - iii. Procedure taken up in Restoration works:-
  - iv. Restored Length:- 34m - 35.30m<sup>3</sup>


## B. For Bridge


1. Damage Location Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works
  - i. Materials being used in restoration works:-
  - ii. Equipment's/Tools being used in Restoration works:-
  - iii. Procedure taken up in Restoration works:-
  - iv. Restored Length:-

## C. Requirement Of New CD/ Bridges

- i. Name of Road:-
- ii. Location/ Chainage:-
- iii. Type of CD Work/ Length required:-

grade (S)

  
20/04/22  
Signature of JE/AE/EE

  
22/4/22  
RE

  
Signature  
(Name of Inspection)