

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 6/6/22	District: Aurangabad
Division : Aurangabad	Length (km): 3.0 KM
Name of the Road: L154 Markdumpur Nahar to Nayki (VR154)	
Scheme/Programme: PMGSY	

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement BT/CC	
a)	Condition of Surfacing CC	U
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	U
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	S

Observation Remarks:-

PCC surface is rough & exposed Aggregate.
BT surface is good condition.

2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N/A
c)	Condition of railings/slab/approach for Bridges	N/A
d)	Condition of Vent Clearance	S

Observation Remarks:-

Hume pipe culvert is in good condition.

3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
Observation Remarks:- Informatory & maintenance board, km & 200m stone & Road signage is fixed in Road.		
4.	Compliance History	
a)	Status of ATR's & any others	-

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

U

Name of Officer:- Ratan Paswan
Designation:- EE

22/6/22
(Signature)
E-E

26/06/2022
EO, Muzer.

Regional Laboratory
Muzaffarpur